

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Sundries	1	\$ 50.00	\$ 50.00
2	Quarter panel n/s clips	6	\$ 5.50	\$ 33.00
3	Front bumper rivets	10	\$ 5.50	\$ 55.00
4	Front door step garnish n/s clips	6	\$ 5.50	\$ 33.00
5	Front door inner trim board n/s clips	8	\$ 5.50	\$ 44.00
6	Front steel wheel n/s	1	\$ 450.00	\$ 450.00
7	Front tyre n/s	1	\$ 280.00	\$ 280.00
8	Front door company sticker n/s	1	\$ 25.00	\$ 25.00
			Total	\$ 970.00

X } n
X } n
30
10
X } n
X } n
X } n
nec
65

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	To remove and refit n/s front tyre to replace n/s front rim. To perform tyre balancing.	0.25	\$ 50.00
4	To remove and refit n/s front door components to replace n/s front door, check and alignment.	0.5	\$ 100.00
5	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
6	To rust proof all affected portions after repair.	0.5	\$ 100.00
7	To remove and refit front n/s undercarriage for replacement of parts.	1	\$ 200.00
8	To conduct computerized wheel alignment.	0.5	\$ 100.00
		Total labour	\$ 3,000.00

600.
30.
X n
60.
600.
30.
X n
X n
1220
1220

Estimate Grand Total	\$ 10,860.25
-----------------------------	---------------------

262822
65
1220
3815.22 4013.22
4543050-1543200 #
04 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature