



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV10780/LEE WEE GIAT
	Reg No/Reg Date	SMJ7982M / 21/03/201
	Date In/Mileage	/ 54320
	Chassis No	MMBSTA13AKH001149
	Engine No	3A92UHN8454
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	PO1 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount	
KAX00008	Credit	22/03/2021/ 15:57	QUD	247 / DonBong	64308					
Description of Goods / Services									3750.00	
E PNT88000	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, REAR BOOT LID, REAR SPOILER, REAR BODY KITS CUT/WELD LH REAR FENDER, REAR FLOOR PANEL, REAR END PANEL, REPAIR RH REAR FENDER, REPAIR RH REAR DOOR							6 X 450		2790
E PNT88000	REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK							(photo)		120.00 ✓
E PNT88000	REMOVE AND REPLACE REAR BODY KITS, REAR SPOILER									160.00 ✓
E PNT88000	REMOVE AND INSTALL PARKING SENSOR TO FACILITATE REPAIR WORK									60.00 ✓
E PNT88000	REMOVE AND INSTALL REAR WINDSCREEN GLASS									240.00 ✓
M SUNDRY	SUPPLY REAR WINDSCREEN SEALANT									80.00 ✓
E PNT98000	PAINT WORK SPRAY REAR FLOOR PANEL, REAR END PANEL, REAR BOOT LID, REAR SPOILER, REAR BUMPER, REAR BODY KITS, LH REAR FENDER, LH REAR TAILAMP HOUSING, LH REAR DOOR, RH REAR FENDER AND AFFECTED PORTION							7 1/2 X 350		3850.00
A 13900099	REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIR WORK							(photo)		2625
M SUNDRY	APPLY BODY SEALANT									450.00 ✓
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM									80 160.00
M SUNDRY	SUPPLY C&C LOGO									30.00 ✓
M SUNDRY	SUPPLY PARKING SENSOR ASSIST							TN		40.00 ✓
M SUNDRY	PERFORM RUST PREVENTION									220.00 ✓
									40 80.00	

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address (AIG Asia Pacific Insurance Pte. Ltd.) and Owner Name & Vehicle Info (KCV10780/LEE WEE GIAT).

Table with 4 columns: Account No (KAX00008), Terms (Credit), Date/Time Printed (22/03/2021/ 15:57), CSE (QUD), Operator (247 / DonBong), and WIP No (64308).

Main table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, and Amount. Includes items like 'TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST' and 'SUPPLY REAR NUMBER PLATE WITH FRAME'.

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10780/LEE WEE GIAT Reg No/Reg Date SMJ7982M / 21/03/201 Date In/Mileage / 54320 Chassis No MMBSTA13AKH001149 Engine No 3A92UHN8454 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P01 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
KAX00008	Credit	22/03/2021/ 15:57	QUD	247 / DonBong	64308				
Description of Goods / Services						Qty	Unit Price	Disc%	Amount
M	GROMMET, TAIL LAMP	*	?	PC		4.00	3.00	23.00	9.24
M	LAMP ASSY, LICENSE PLATE		X	PC		2.00	51.00	23.00	78.54
M	REFLECTOR LH		X	PC		1.00	23.00	23.00	17.71
M	REFLECTOR RH		X	PC		1.00	23.00	23.00	17.71
M	EMBLEM MIVEC TECHNOLOGY		X	PC		1.00	30.00	00.00	30.00
M	PANEL, QTR, OTR LH		PC			1.00	759.00	23.00	584.43
M	EXTN, QTR PANEL, UPR OTR LH		PC			1.00	118.00	23.00	90.86
M	PANEL, RR COMB LAMP HSG, LH		PC			1.00	60.00	23.00	46.20
M	STOPPER, WINDSHIELD GLASS		PC			2.00	3.00	23.00	4.62
M	SPACER, RR WINDOW		PC			3.00	9.00	23.00	20.79

Estimate

SURVEYOR NAME: Steve (LKK) 22/3/21, 4.00pm

SURVEYOR SIGNATURE: OO-AM AL

DATE: Excess - ?

REMARKS: P/P

By Bel

18 days

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey

Confirm & accepted by: [Signature]
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

Nett	16,197.29
7% GST on	1133.81
Total Payable	17,331.10

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.