



Vfix Auto Pte Ltd
26 Chia Ping Road
Singapore 619977
Email: contact@vfixauto.com.sg
Tel: 64552957 Fax: 68628669
UEN / GST REG No.: 201830761R

ESTIMATE

DATE : 29/3/2021
ACC DATE : 18/3/2021
POLICY NO :
SHEET NO. 1 OF 1 SHEET

Attention: Motor Claim Department

RE : VEHICLE NO : XD6344M Isuzu (Lonpac)

S/NO.	QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	1	Front Cabin Head <i>bu</i>		60,000.00
2	1	AirCond Dryer ?		113.00
3	1	Front Cabin Jack <i>ds</i>		895.00
4	2	Front Cabin Jack Hydraulic Pipe ?	150.00	300.00
5	1	Dashboard <i>de</i>		1,800.00
6	1	Glove Box ?		450.00
7	1	Dashboard Inner Beam ?		684.00
8	1	Aircond Evaporator ?		1,880.00
9	1	Aircond Blower ?		2,600.00
10	1	Turbo Intercooler ?		4,184.00
11	1	Radiator ?		2,560.00
12	1	Radiator Cowling Inner ?		420.00
13	1	Radiator Cowling Outer ?		380.00
14	1	Radiator Fan Blade ?		135.00
15	2	Engine Oil Pipe ?	200.00	400.00
16	1	Front Absorber LH <i>ms</i>		380.00
17	1	Front Absorber Mounting <i>ms</i>		60.00
18	2	Leaf Spring ?	1,200.00	2,400.00
19	4	Leaf Spring U Board ?	200.00	800.00
20	1	Leaf Spring Top Mounting ?		180.00
21	2	Leaf Spring Bracket ?	320.00	640.00
22	1	Front Axle ?		2,200.00
23	1	Front Knuckle LH ?		1,300.00
24	1	Front Knuckle LH Bearing ?		175.00
25	1	Front Brake Drum ?		670.00
26	1	Front King Pin LH ?		320.00
27	1	Front Brake Chamber LH ?		770.00
28	2	Front Brake Hose ?	165.00	330.00
29	1	Steering Shaft ?		1,100.00
30	2	Steering Shaft Joint ?	200.00	400.00
31	1	Steering Draglink ?		420.00
32	1	Steering Box ?		1,720.00
33	1	Power Steering Tank ?		200.00
34	1	Radiator Tank ?		210.00
35	1	Cabin Support Bracket Rear ?		1,200.00
36	1	Cabin Switch Rear ?		100.00
37	2	Cabin Rear Absorber ?	180.00	360.00
38	2	Cabin Air Ballon Rear ?	242.00	484.00
39	1	Cabin Rear Handler ?		650.00
40	1	Cabin Rear Jack Motor ?		1,300.00
41	1	Aircond Condenser <i>st</i>		1,100.00
42	1	Aircond Dryer ?		350.00
43	1	Aircond Fan Assy ?		650.00
44	1	Aircond Pipe ?		370.00
45	1	Aircond Suction Pipe ?		450.00
46	1	Aircond Discharge ?		478.00
				98,568.00

S/NO.	QTY	LABOUR & MISCELLANEOUS :	AMOUNT S\$
1	1	To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	5,000.00 <i>2500</i>
2	1	To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	5,000.00 <i>1500</i>

\$ 10,000.00

ISSUED BY

VERIFIED BY

ESTIMATE CONFIRMED AND ACCEPTED BY

KOH WENG SHENG

KEN TAN

NAME, SIGNATURE, DATE SIGNED

Rasul

Hp 90010068

14 days

L/S

22/03/2021 @ 1700

EXCESS: TBA

REVERT

Resurvey after repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: