

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel: +65 6679 1146

email:ben@allswellmotor.com.sg

Not Notified
21 Sep @ 2950h
Resurvey After Paint
5 days

(3rd party claim against AIG insured GBK9197A
POA : 19.03.2021

Estimate repair

Vehicle No. : SUN9408M
Make & Model : Carolla Auto
Chassis No. : _____
Date of survey : _____

Submitted by : Ben
COE expiry : 22.04.2023
Engine No. : _____

S/No	Part Description	Qty	Unit	Price	Disposition by
01	LH fender 456 R1	01	\$600.00		✓
02	Bumper front 757.20 R1	01	\$900.00		✓
03	Bumper front 485 R1/LM	01	\$720.00		✓
04	LH Headlamp B20	01	\$460.00		✓
05	Support panel R1	01	\$500.00		✓
06	LH water tank 85.50 R1	01	\$190.00		✓
07	LH main shield nil	01	\$192.00		✓
08	Front license plate nil	01	\$40.00		✓
	Special note			256	
01	Clips & retaining studs @ 40 / pkt	01	\$40.00		✓
	Labour Description				
01	Disassembly / Assembly of all affected parts (headlamp) bumper fender / bumper / shield and etc	01	\$700.00		600
02	Panel knocking of support panel	01	\$300.00		
03	Spray painting of all affected parts bumper fender bumper	01	\$800.00		750

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost:

FR inner cover 14830 mis ✓

LKK Auto Consultants hence notify

additional labour cost:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: