



S THREE AUTOMOTIVE RECOVERY PTE LTD

MOTOR CLAIM DEPT.

T/P VEH. NO. : SHC7450C

QUOTE REPORT 1st QUOTATION

OWNER'S PARTICULAR

*NOT Authorized
11 Sep 83750/h
Presuming After Paint
3days*

JOB NO. : _____

NAME : HO CHING PENG

CONTACT : _____

ADDRESS : 12A LORNIE ROAD

SINGAPORE 298696

LICENSE NO. : SFF2345P TRANS.

MAKE / MODEL : MERCEDES S300L

OWNER'S INSURER : AIG

CHASSIS NO. : _____

ENGINE NO. : _____

JOB-CODE : TP S/A : JOEY

ACCIDENT DATE : 19-Mar-21

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR-DISP	REV. PRICE
1 REAR BOOTLID	1.00	<i>R</i> 3100.00	10.00	2790.00	Y	<i>X</i>
2 REAR BOOTLID S300 EMBLEM	1.00	<i>fan</i> 75.00	10.00	67.50	Y	<i>X</i>
3 REAR BOOTLID LOGO	1.00	<i>na</i> 78.00	10.00	70.20	Y	<i>X</i>
4 REAR BOOTLID 7G TRONIC EMBLEM	1.00	<i>na</i> 122.00	10.00	109.80	Y	<i>X</i>
5 REAR BOOTLID INNER LOCK MECHANISM	1.00	<i>R</i> 780.00	10.00	702.00	Y	<i>X</i>
6 REAR BOOTLID CATCH	1.00	<i>R</i> 232.00	10.00	208.80	Y	<i>X</i>
7 REAR BOOTLID WEATHERSTRIP	1.00	<i>sn</i> 228.00	10.00	205.20	Y	<i>X</i>
8 REAR BOOTLID INNER TRIM	1.00	<i>sn</i> 620.00	10.00	558.00	Y	<i>X</i>
9 REAR BOOTLID CHROME MOULDING	1.00	<i>sn</i> 580.00	10.00	522.00	Y	<i>X</i>
10 REAR BOOTLID SIDE GARNISH INNER RH	1.00	<i>sn</i> 176.00	10.00	158.40	Y	<i>X</i>
11 REAR BUMPER <i>1840</i>	1.00	<i>R</i> 2100.00	10.00	1890.00	Y	<i>✓</i>
12 REAR BUMPER SIDE RETAINER LH	1.00	<i>sn</i> 148.00	10.00	133.20	Y	<i>X</i>
13 REAR BUMPER SIDE RETAINER RH <i>120</i>	1.00	<i>CM</i> 148.00	10.00	133.20	Y	<i>2</i>
14 REAR BUMPER REINFORCEMENT BEAM <i>650</i>	1.00	<i>R</i> 986.00	10.00	887.40	Y	<i>2</i>
15 REAR BUMPER REINFORCEMENT BRACKET	1.00	<i>R</i> 376.00	10.00	338.40	Y	<i>X</i>
16 REAR BUMPER TOW COVER	1.00	<i>sn</i> 48.00	10.00	43.20	Y	<i>X</i>
17 REAR BUMPER INNER PLASTIC BEAM	1.00	<i>sn</i> 832.00	10.00	748.80	Y	<i>X</i>
18 TAILLAMP RH <i>Pr? 650</i>	1.00	<i>CM</i> 2140.00	10.00	1926.00	Y	<i>✓</i>
19 TAILLAMP BRACKET RH	1.00	<i>sn</i> 680.00	10.00	612.00	Y	<i>X</i>
20 TAILLAMP MOULDING RH	1.00	<i>sn</i> 320.00	10.00	288.00	Y	<i>X</i>
21 REAR END PANEL	1.00	<i>R</i> 1039.00	10.00	935.10	Y	<i>X</i>
22 REAR END PANEL TOP GARNISH	1.00	<i>sn</i> 265.00	10.00	238.50	Y	<i>X</i>
23 REAR EXHUAUST SHIELD <i>235</i>	1.00	<i>na</i> 283.00	10.00	254.70	Y	<i>2</i>
24 REAR SPARE TYRE FIBRE PANEL	1.00	<i>sn</i> 1080.00	10.00	972.00	Y	<i>X</i>
25 KEYLESS SENSOR	1.00	<i>sn</i> 380.00	10.00	342.00	Y	<i>X</i>
TOTAL (PARTS) :			16816.00		15134.40	

SPECIAL NETT ITEM

1 REAR BUMPER CLIPS	1.00	<i>na</i> 80.00	0.00	80.00	Y	<i>50/h</i>
2 REVERSE SENSOR WITH HOLDERS <i>Pr?</i>	<i>260</i> 1.00	<i>sho</i> 1200.00	0.00	1200.00	Y	<i>2</i>
3 REVERSE SENSOR WIRE HARNESS <i>250</i>	<i>CM</i> 1.00	<i>na</i> 790.00	0.00	790.00	Y	<i>X</i>
4 REAR END PANEL SEALANT	1.00	<i>na</i> 100.00	0.00	100.00	Y	<i>X</i>

111/01007195/16
 C

SPARE TYRE PANEL SEALANT
 R BOOTLID INNER TRIM CLIPS

	1.00	un	280.00	0.00	280.00	Y	X
	1.00	un	80.00	0.00	80.00	Y	X
TOTAL (PARTS) :					2530.00		2530.00
LABOUR							
1	1.00		1200.00	0.00	1200.00	Y	2501
2	1.00		1200.00	0.00	1200.00	Y	401
3	1.00		150.00	0.00	150.00	Y	201
4	1.00	un	150.00	0.00	150.00	Y	X
5	1.00	un	150.00	0.00	150.00	Y	X
6	1.00		150.00	0.00	150.00	Y	301
7	1.00	un	150.00	0.00	150.00	Y	X
8	1.00	un	380.00	0.00	380.00	Y	X
TOTAL (LABOUR) :			3530.00		3530.00		
TOTAL PARTS & LABOUR			22876.00		21194.40		

EXCESS : : \$S _____

NO. OF DAY : 2-3 days

RE-SURVEY : BEFORE / AFTER PAINTING

PART BY PART OR LUMP-SUM : \$S _____

DATE OF SURVEY : 23/3/21

SURVEY BY : Kenneth

CONTACT NO : _____ FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before respray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



S THREE AUTOMOTIVE RECOVERY PTE LTD

MOTOR CLAIM DEPT.

TP VEH. NO : SHC7450C

ESTIMATE REPORT 1st QUOTATION

OWNER'S PARTICULAR

NAME : HO CHING PENG
 ADDRESS : 12A LORNE ROAD
 SINGAPORE 298696
 LICENSE NO. : SFF2345P TRANS.
 MAKE / MODEL : MERCEDES S300L
 OWNER'S INSURER : AIG
 JOB-CODE : TP S/A : JOEY

JOB NO : _____

CONTACT : _____

CHASSIS NO : _____

ENGINE NO : _____

ACCIDENT DATE : 19-Mar-21

SUPPLYMENTARY

1	REAR BUMPER LOWER BRACKET LH	1.00	CM	90.00	10.00	81.00	Y	<u> </u>
2	REAR BUMPER LOWER BRACKET RH	1.00	CM	90.00	10.00	81.00	Y	<u> </u>
3	TAILLAMP SIDE GARNISH COVER RH	1.00	017	85.00	10.00	76.50	Y	<u> </u>

EXCESS : : \$S _____

NO. OF DAY : _____

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : \$S _____

DATE OF SURVEY : ____/____/____

SURVEY BY : _____

CONTACT NO : _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.