

ASS. REC. BY:

Steve


CS/CTI21003697/Eqf3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD-RES / EVA / INV / MY
 To Inspect Vehicle No: GBJ 2607K
 at Workshop m/s EFFICIENT MOTOR
 of _____
 Insured: GBA 5888T
 Policy No. DMCVSNA00029462000
 Claims No. SNM21D201602C02
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 12 days Res.: Yes or No
 Cum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBJ 2607K Yr Regn: 28/2/19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Nissan NV350 c.c. 2488
 Colour: White A/C: Insured / Std / NI / N
 Sp. Reading: 95197 T/Radio: Insured / Std / NI / N
 Eng/No: _____
 C/No: JNIM C2E: 262 0030851
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195R15C
 R: _____
 BS (OUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 22/3/21 D.O.I. 23/3/21
 Survey held at Efficient Motor
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>MIV-63K</u>
<u>23/03/21</u>	<u>@1.55PM REVISED IA TO KAH LEONG VIA MERIMEN</u>
<u>09/04/21</u>	<u>Steve finalised final fig \$11279.83, 12 days (Red \$22080.05, 66%)</u>

Date/Time, File, Pass to?

☐ : Prel. Report

14/04 Typist

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 12Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS. \$

Photo

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Work and (\$

Approved: MER-TPFinal Sum / L.C. / F: 11279.83

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBJ2607K

MAKE & MODEL : NISSAN / NV350 PANEL VAN 5DR 2.5 SAT

CHASSIS NO : JN1MC2E26Z0030851

DATE : 22 MAR 2021

CLAIM TYPE : TP CLAIM

D.O.A : 22 MAR 2021

TO : CHINA TAIPING

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	REAR BUMPER / <i>OD</i>		\$ 667.20	\$ 667.20
2	<i>82</i>	REAR BUMPER SIDE CLIP LH/RH <i>(RH)</i>	<i>/ n/c</i>	\$ 12.10	\$ 72.60
3	1	REAR BUMPER STEP PANEL <i>/ OR</i>		\$ 252.30	\$ 252.30
4	1	REAR END PANEL OUTER <i>/ OD</i>		\$ 360.90	\$ 360.90
5	1	TAILGATE <i>/ OD</i>		\$ 2,280.00	\$ 2,280.00
6	1	TAILGATE LOCK LOWER <i>/ BT</i>		\$ 528.60	\$ 528.60
7	1	TAILGATE LOCK UPPER <i>X</i>		\$ 178.80	\$ 178.80
8	1	TAILGATE LOCK COVER <i>X / CUT</i>		\$ 84.00	\$ 84.00
9	1	TAILGATE LOCK ACTUATOR <i>X</i>		\$ 408.40	\$ 408.40
10	1	TAILGATE STRIKER <i>X</i>		\$ 51.50	\$ 51.50
11	1	TAILGATE WEATHERSTRIP <i>/ TN</i>		\$ 228.00	\$ 228.00
12	1	TAILGATE CHROME GARNISH <i>X</i>		\$ 535.70	\$ 535.70
13	2	TAILGATE ABSORBER LH/RH <i>X</i>		\$ 215.90	\$ 431.80
14	1	TAILGATE INNER TRIM BOARD <i>X</i>		\$ 220.00	\$ 220.00
15	1	TAILGATE LOGO <i>/ n/c</i>		\$ 115.20	\$ 115.20
16	1	TAILGATE EMBLEM "NV350 URBAN" <i>/ n/c</i>		\$ 156.00	\$ 156.00
17	1	TAILGATE INNER CENTER METAL COVER <i>X</i>		\$ 108.00	\$ 108.00
18	<i>21</i>	TAIL LAMP LH/RH <i>(RH) OR</i>		\$ 288.40	\$ 576.80
19	2	TAILGATE FEMALE DOVETAIL <i>X</i>		\$ 58.70	\$ 117.40
20	2	TAILGATE MALE DOVETAIL <i>X</i>		\$ 58.70	\$ 117.40
21	1	THIRD BRAKE LIGHT <i>X</i>		\$ 237.50	\$ 237.50
22	1	REAR WIPER ASSY <i>X</i>		\$ 242.00	\$ 242.00
23	2	REAR NUMBER PLATE LAMP <i>X</i>		\$ 96.00	\$ 192.00
24	1	REAR FENDER RH <i>X R</i>		\$ 1,793.40	\$ 1,793.40
25	1	TAIL LAMP PANEL RH <i>X R</i>		\$ 465.30	\$ 465.30
26	1	FRONT PANEL <i>/ OD</i>		\$ 1,227.50	\$ 1,227.50
27	1	FRONT BUMPER <i>/ BR</i>		\$ 571.90	\$ 571.90
28	2	FRONT BUMPER SIDE RETAINER LH/RH <i>/ OR</i>		\$ 181.00	\$ 362.00
29	2	FRONT BUMPER CENTRE GRILLE <i>X</i>		\$ 912.00	\$ 1,824.00
30	2	FRONT FOG LAMP GARNISH LH/RH <i>X</i>		\$ 130.10	\$ 260.20
31	1	FRONT BUMPER REINFORCEMENT <i>X</i>		\$ 705.00	\$ 705.00
32	1	FRONT GRILLE <i>/ BR</i>		\$ 940.00	\$ 940.00
33	1	FRONT GRILLE EMBLEM <i>/ n/c</i>		\$ 120.70	\$ 120.70
34	2	HEADLAMP ASSY LH/RH <i>/ BR</i>		\$ 624.00	\$ 1,248.00
35	1	INTERCOOLER <i>X</i>		\$ 3,360.70	\$ 3,360.70
36	1	INTERCOOLER GARNISH <i>X</i>		\$ 324.20	\$ 324.20
37	1	OIL COOLER <i>X</i>		\$ 1,392.00	\$ 1,392.00
38	1	OIL COOLER GARNISH <i>X</i>		\$ 324.20	\$ 324.20
39	1	AIR GUIDE LOWER <i>X</i>		\$ 115.20	\$ 115.20
40	1	AUTO TRANSMISSION COOLER PIPE <i>X</i>		\$ 1,344.80	\$ 1,344.80
41	1	RADIATOR <i>X</i>		\$ 1,560.00	\$ 1,560.00
42	1	RADIATOR FAN BLADE <i>X</i>		\$ 528.00	\$ 528.00
43	1	CONDENSER & FAN ASSY <i>X</i>		\$ 2,400.00	\$ 2,400.00
44	1	AIR CON LIQUID PIPE <i>X</i>		\$ 768.00	\$ 768.00
45	2	CORNER PANEL LH/RH <i>X</i>		\$ 468.00	\$ 936.00
				\$ 27,639.90	\$ 30,733.20

TOTAL PRICE	\$	30,733.20
LESS 10%	\$	3,073.32
SUB TOTAL PRICE	\$	27,659.88

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	REAR BUMPER CLIPS <i>APC</i>		\$ 50.00	\$ <i>30</i> 50.00
2	1	70 KM/H STICKER <i>APC</i>		\$ 20.00	\$ 20.00
3	1	REVERSE SENSOR <i>SHAN</i>		\$ 200.00	\$ 200.00
4	1	REAR NO. PLATE <i>X</i>		\$ 45.00	\$ 45.00
5	1	PAN PACIFIC METAL PLATE <i>APC</i>		\$ 80.00	\$ <i>50</i> 80.00
6	1	BACK DOOR GLASS SEALANT <i>APC</i>		\$ 80.00	\$ <i>40</i> 80.00
7	1	REAR PANEL CHECKER PLATE <i>BT</i>		\$ 80.00	\$ 80.00
8	1	FRONT BUMPER CLIPS SET <i>APC</i>		\$ 50.00	\$ <i>30</i> 50.00
9	1	FRONT GRILLE CLIPS SET <i>APC</i>		\$ 50.00	\$ <i>10</i> 50.00
10	1	FRONT NO. PLATE <i>BT</i>		\$ 45.00	\$ <i>35</i> 45.00
TOTAL S/NETT				\$ 700.00	\$ 700.00

Labour Charges

1	To cut/weld panels,panel beat & align REAR portion, remove & replace damaged parts.	\$ 1,300.00	<i>800 900</i>
2	To apply anti rust coat and Tuff Kote repaired areas.	\$ 100.00	<i>30</i>
3	To check and rectify lighting & wiring.	\$ 50.00	<i>30</i>
4	To remove & replace reverse sensor.	\$ 100.00	<i>30</i>
5	To Spray painting for Rear Portions & affected areas.	\$ 1,000.00	<i>800</i>
6	To remove & transfer tailgate components.	\$ 150.00	<i>50</i>
7	To remove and replace rear windscreen glass.	\$ 150.00	<i>120</i>
8	To remove and refit and align exhaust silencer.	\$ 100.00	<i>X</i>
9	To conduct water leakage tests to ensure proper air and sealing.	\$ 50.00	<i>30</i>
10	To cut/weld panels,panel beat FRONT portion, remove & replace damaged parts.	\$ 1,000.00	<i>800</i>
11	To Spray painting Front Portion & other affected areas.	\$ 800.00	<i>400</i>
12	To remove and refit radiator,condenser,other components & top up A/C gas.	\$ 200.00	<i>X</i>
TOTAL LABOUR			\$ 5,000.00
Total Cost of Repairs			\$ 33,359.88

(Total parts + Total S/Nett + Total Labour Cost)

Steve (LKK) with AL

23/3/21, 10.00 am

L/S

My AL sy

12 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/03/2021 14:49 (SGT)
Date of Accident 22/03/2021 09:45 (SGT)
Exact Location of Accident 292A Compassvale St, Singapore 540292
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBJ2607K

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner PAN PACIFIC VAN & TRUCK LEASING PTE LTD
Company Reg No 2XXXXX635R
Email Address ppemclaims@gmail.com
Mobile Phone No (Phone) +65-89529701
Alternative Phone No (Office) +65-62840827

VEHICLE PARTICULARS

Manufacturer Nissan
Model Nv350
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Manual
CC 2488

INSURANCE COMPANY

Name of Insurance Company India International Insurance Pte Ltd
Type of Coverage Comprehensive
Fleet Policy Yes
Policy Number D19MFL0005549_01
Cover Note Number -

DRIVER

Name of Driver HONG RONGYAO
NRIC No SXXXX350C



Date Of Birth	10/11/1983
Occupation	Outdoor
Date Of Driving Pass	16/03/2005
Driving experience	16 YEARS
Gender	Male
Mobile Number	(Phone) +65-89529701
Alt. Phone Number	-
Email Address	SKYTISTAN35@GMAIL.COM
Address	BLK 299B COMPASSVALE STREET #14-106
Address complement	-
Postcode	542299
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 22/3/21 @ 0945HRS I WAS DRIVING ALONG COMPASSVALE ST ONBOARD MY VEHICLE GBJ2607K ALONE. MY VEHICLE WAS ON STATIONARY AT THE CROSS JUNCTION ON THE EXTREME LEFT LANE. THERE WAS A TOYOTA SIENTA SLV5375C AHEAD OF ME. WHILE WAITING FOR THE LIGHT TO TURN GREEN AT MY FAVOR, A WHITE VAN BEARING THE PLATE NO GBA5888T REAR ENDED ME AND CAUSE MY VEHICLE TO EDGE FORWARD AND COLLIDED ONTO THE FRONT REAR BUMPER. NOBODY EXCEPT FOR ME SUSTAINED INJURY. I SUFFERED FROM LOWER BACK INJURY. DRIVER EXCHANGED DETAILS.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SLV5375C
Vehicle Manufacturer	Toyota
Vehicle Model	Sienta
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver	MAR WENG WONG
NRIC No	SXXXX364I
Contact Number	(Phone) +65-98393838
Address	BLK 1F CANTONMENT ROAD #41-63
Address complement	-
Postcode	085601
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2:

Vehicle Registration Number	GBA5888T
Vehicle Manufacturer	Volkswagen
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	KOH TENG KIT
NRIC No	SXXXX030H
Contact Number	(Phone) +65-97347300
Address	BLK 782E WOODLANDS CRESCENT #13-367
Address complement	-
Postcode	735782
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS:

INJURED 1

Name of injured person	HONG RONGYAO
Address	BLK 299B COMPASSVALE STREET #14-106
Address Complement	-
Post Code	542299
Approximate Age Years Old	37
Injuries Sustained	LOWER BACK INJURED
Injured person in which vehicle?	GBJ2607K
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

On 27/3/21 @ 0945hrs I was driving along Compressor St entered my vehicle G852607K etc. My vehicle was stationary at the cross junction on the extreme left lane. There was a Toyota Sienna SLV 5375C ahead of me. While waiting for the light to turn green at my front, a white van bearing the plate no G8A5888T rear ended me and cause my vehicle to edge forward and collided onto the front rear bumper. Nobody except for me sustained injury. I suffered from lower back injury. Driver exchanged details.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	635R

Vehicle Details

Vehicle No.:	GBJ2607K
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Mar 2021
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 5DR 2.5 SAT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	YD25042450B
Chassis No.:	JN1MC2E26Z0030851
Maximum Power Output:	-
Open Market Value:	\$26,390.00
Original Registration Date:	28 Feb 2019
First Registration Date:	28 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$1,320.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	27 Feb 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$26,914.00
COE Rebate Amount:	\$21,346.00
Total Rebate Amount:	\$21,346.00

The information contained herein is correct as at 22 Mar 2021

OK