

ASS. REC. BY:

REF:

CL3 / CT1 21003704 / T1293

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SAC 6392T Yr Regn: 2015, Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Optima c.c. 1685Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 566133 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNA GM414 MF 5574975

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R15R: 205/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 23/3/21Survey held at Premier Taxi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.H. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS. ____ SI

Photos

Others

TOTAL

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

22-Mar-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6392 T

2 pcs	Front n/s & o/s head lamp @ \$1028.00	n/s Xun	\$	2,056.00	o/s cora
1 pc	Front bumper emblem		\$	44.00	X
1 pc	Front bumper		\$	531.00	de
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	n/s Xun	\$	32.00	o/s n/s
2 pcs	Front bumper n/s & o/s upper bracket @ \$16.00		\$	32.00	X
2 pcs	Front bumper n/s & o/s support bracket @ \$16.00		\$	32.00	X
1 pc	Front bumper reinforcement		\$	328.00	X
1 pc	Front bumper sponge		\$	110.00	in?
1 pc	Front bumper o/s protector @ \$51.00		\$	51.00	cut
1 pc	Front bumper o/s fog lamp cover @ \$66.00		\$	66.00	cut
1 pc	Front bumper lower stiffer		\$	134.00	X
1 pc	Front bumper centre grille		\$	174.00	X
1 pc	Support panel		\$	645.00	X
1 pc	Bonnet grille		\$	385.00	X
1 pc	Front o/s fender @ \$384.00		\$	384.00	X
1 pc	Front o/s fender inner shield @ \$120.00		\$	120.00	?
1 pc	Front o/s rim @ \$246.00		\$	246.00	X damage
1 pc	Front o/s wheel cover @ \$116.00		\$	116.00	X old design
			\$	5,486.00	
		Less 10%	\$	548.60	
			\$	4,937.40	

22-Mar-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6392 T

S/NETT

1 pc	Front no. plate with casing	\$	30.00 X
1 set	Front n/s fender inner shield clips	\$	28.00 X
1 set	Front bumper clips	\$	48.00 <i>30 ne</i>
1 pc	Front o/s fender sticker	\$	60.00 X
2 pcs	Front n/s & o/s head lamp lower clip	\$	12.00 X
2 pcs	Front n/s & o/s head lamp side clip	\$	6.00 ?
1 pc	Tyre (Tyre Brand: Achilles) @ \$200	\$	200.00 X
	To check wheel alignment	\$	80.00 X
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same etc	\$	800.00 <i>200</i>
	To putty and spray painting on front bumper, bonnet, bonnet grille, front o/s fender	\$	800.00 <i>200</i>
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 X
		\$	<u>7,301.40</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphir 97495749
WP' 23/3/21 @ 12pm
45 Remay after repair
Tanphir@lkhauto.com
2 days

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	09 Jan 2015 / 08:44:29	Receipt No.:	AACCK001-AX239-150109-000001
Asset Type:	Vehicle	Transaction Amount:	\$65,919.00
Asset ID:	SHC6392T	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150109084429229127		

Vehicle No.:	SHC6392T
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)

First Registration Date:	09 Jan 2015
Original Registration Date:	09 Jan 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5574975
Engine No.:	D4FDEH313255

Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2014
Open Market Value:	\$20,566.00
Minimum PARF Benefit:	\$7,975.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	09 Jan 2015 08:44:29
COE No.:	2015010901001425Z
COE Expiry Date:	08 Jan 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount	\$52,486.00
Lifespan Expiry Date:	08 Jan 2023