

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

22-Mar-21

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6392 T

2 pcs	Front n/s & o/s head lamp @ \$1028.00	1/5 Xun	\$	2,056.00	1028	o/s core -
1 pc	Front bumper emblem		\$	44.00	X	nn
1 pc	Front bumper		\$	531.00	de -	
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	1/5 Xun	\$	32.00	o/s ret - 16	
2 pcs	Front bumper n/s & o/s upper bracket @ \$16.00		\$	32.00	X	X
2 pcs	Front bumper n/s & o/s support bracket @ \$16.00		\$	32.00	X	nn
1 pc	Front bumper reinforcement		\$	328.00	X	
1 pc	Front bumper sponge		\$	110.00	nn	Xun
1 pc	Front bumper o/s protector @ \$51.00		\$	51.00	cut	
1 pc	Front bumper o/s fog lamp cover @ \$66.00		\$	66.00	cut	
1 pc	Front bumper lower stiffer		\$	134.00	X	
1 pc	Front bumper centre grille		\$	174.00	X	
1 pc	Support panel		\$	645.00	X	nn
1 pc	Bonnet grille		\$	385.00	X	X
1 pc	Front o/s fender @ \$384.00		\$	384.00	X	
1 pc	Front o/s fender inner shield @ \$120.00		\$	120.00	?	
1 pc	Front o/s rim @ \$246.00		\$	246.00	X	nn
1 pc	Front o/s wheel cover @ \$116.00		\$	116.00	X	nn
			\$	5,486.00		
Less 10%			\$	548.60		
			\$	4,937.40		

1692  
10% - 1522.80

22-Mar-21

# ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6392 T

## S/NETT

1 pc	Front no. plate with casing	\$	30.00	x mu
1 set	Front n/s fender inner shield clips	\$	28.00	x an
1 set	Front bumper clips	\$	48.00	30 ne
1 pc	Front o/s fender sticker	\$	60.00	x
2 pcs	Front n/s & o/s head lamp lower clip	\$	12.00	x
2 pcs	Front n/s & o/s head lamp side clip	\$	6.00	? x
1 pc	Tyre (Tyre Brand: Achilles) @ \$200	\$	200.00	x
	To check wheel alignment	\$	80.00	x 30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	x un
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same etc	\$	800.00	200
	To putty and spray painting on front bumper, bonnet, bonnet grille, front o/s fender	\$	800.00	200
	To apply rustproofing on the repaired and replaced panels.	\$	120.00	x un.
			<u>\$</u>	<u>7,301.40</u> 400.

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749  
WP' 23/3/21 @ 12pm  
45 Remun after repair  
tanpin@lkhauto.com.  
2 days

1522.80  
30  
400  
1952.80  
41581550  
2 days #