

Lim Tien Siong

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 22 Mar 2021)

Parts: 143 **HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: ComfortDelGro Engineering Pte Ltd/SHD3390M/22/03/2021 13:39

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR DOOR APPS STICKER RH	0.00	0.00	*80.00 F <i>sub</i>
2	1		*REAR WHEEL CAP RH	20.00	0.00	*217.20 FL <i>ut</i>
Sub Total (\$\$)						297.20
- List Item Discount on L Items (\$\$)						43.44
Total Parts (\$\$)						253.76

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHD3390M/22/03/2021 13:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

217.2
20% 173.76
SN 80

Lim Tien Siong

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

Amount

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$)

✓ 11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING - REAR FENDER ARCH RH ETC

New

280

300.00

2 SPRAY SPRAYING - ROCKER PANEL GARNISH RH ETC

New

600

900.00

Gross Labour Cost (\$)

1,200.00

ComfortDelGro Engineering Pte Ltd/SHD3390M/22/03/2021 13:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97495747
- up' 23/3/21 @ Kpu
L/S Resurvey after repair
tanpin @ 11h and 11h
- 2 days
4

1144.76
458900

02 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: