

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

NTUC INCOME INSURANCE CO-OPERATIVE LTD	DAMAGE ASSESSMENT REPORT						
### ### ### ### ### ### ### ### ### ##		NTUC INCOME INSURANCE CO-OPERATIVE LTD			CS/INC21003720/Atf3n2		
Insured Veh. SLQ 6258C Veh. Inspected SMS 2644A		#05-01 NTUC TRA		Date	11/06/2021		
Insured Veh. SLQ 6258C		ATTN: CHARLOTT	E CHEW	Code	: INC		
Policy No.	1.	Policy Particulars :- THIRD PARTY CLAIM					
Claim No. MT/1125301-001 Excess (\$) 0.00 Assign From ANNIE KOH Assign Date 23/03/2021		Insured Veh.	SLQ 6258C	Veh. Inspected	SMS 2644A		
Assign From		Policy No.		Coverage (\$)	0.00		
2. Vehicle Particulars & Condition Make & Model HONDA ACCORD C.C 1498 Engine No. HIDDEN Year of Reg. 2020 Chassis No. MRHCV1650KP000022 Colour WHITE Odometer 15678 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance		Claim No.	MT/1125301-001	Excess (\$)	0.00		
Make & Model		Assign From	ANNIE KOH	Assign Date	23/03/2021		
Engine No. HIDDEN Chassis No. MRHCV1650KP000022 Colour WHITE Odometer 15678 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance	2. Vehicle Particulars & Condition						
Chassis No. MRHCV1650KP000022 Colour WHITE Odometer 15678 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance		Make & Model	HONDA ACCORD	c.c	1498		
Odometer 15678 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance		Engine No.	HIDDEN	Year of Reg.	2020		
Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance		Chassis No.	MRHCV1650KP000022	Colour	WHITE		
3. Conditions of Tyres R/H Front Tyre 225/50 R17 MICHELIN 6 mm		Odometer	15678 KM	Steering	IN ORDER		
3. Conditions of Tyres Size		Brakes	IN ORDER	Modification	SPORTS RIM		
R/H Front Tyre 225/50 R17 MICHELIN 6 mm L/H Front Tyre 225/50 R17 MICHELIN 6 mm R/H Rear Tyre 225/50 R17 MICHELIN 6 mm L/H Rear Tyre 225/50 R17 MICHELIN 6 mm L/H Rear Tyre 225/50 R17 MICHELIN 6 mm L/H Rear Tyre 225/50 R17 MICHELIN 6 mm 4.		General	GOOD				
R/H Front Tyre 225/50 R17 MICHELIN 6 mm L/H Front Tyre 225/50 R17 MICHELIN 6 mm R/H Rear Tyre 225/50 R17 MICHELIN 6 mm L/H Rear Tyre 225/50 R17 MICHELIN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 22/03/2021 Inspect Date / Time 23/03/2021 (11:08 AM) Survey held at CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	3.		Condition	ons of Tyres			
L/H Front Tyre 225/50 R17 MICHELIN 6 mm R/H Rear Tyre 225/50 R17 MICHELIN 6 mm L/H Rear Tyre 225/50 R17 MICHELIN 6 mm 4.			Size	Make	Balance		
R/H Rear Tyre		R/H Front Tyre	225/50 R17	MICHELIN	6 mm		
L/H Rear Tyre 225/50 R17 MICHELIN		L/H Front Tyre	225/50 R17	MICHELIN	6 mm		
4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 22/03/2021 Inspect Date / Time 23/03/2021 (11:08 AM) Survey held at CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		R/H Rear Tyre	225/50 R17	MICHELIN	6 mm		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. General Information Accident Date 22/03/2021 Inspect Date / Time 23/03/2021 (11:08 AM) Survey held at CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 Table 10 Autobay 10 Auto		L/H Rear Tyre	225/50 R17	MICHELIN	6 mm		
5. General Information Accident Date 22/03/2021 Inspect Date / Time 23/03/2021 (11:08 AM) Survey held at CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	4.	4. Description of Damages					
5. General Information Accident Date 22/03/2021 Inspect Date / Time 23/03/2021 (11:08 AM) Survey held at CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION					
5. General Information Accident Date 22/03/2021 Inspect Date / Time 23/03/2021 (11:08 AM) Survey held at CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair							
Accident Date 22/03/2021 Inspect Date / Time 23/03/2021 (11:08 AM) Survey held at CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		DAMAGES SEE DI	ETAILS.				
Accident Date 22/03/2021 Inspect Date / Time 23/03/2021 (11:08 AM) Survey held at CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	-						
Survey held at CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	5.	Assident Date			22/02/2024 / 44,09 AM \		
1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair				inspect Date / Time	23/03/2021 (11.06 AWI)		
5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		.					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	50						
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	Ja.						
	5b.		Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days		ESTIMATED NORI	MAL PERIOD FOR REPAIR:	5 Wo	rking Days		