

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

22/03/2021

TP ANC

Denise

Accident date:

Estimated repair cost for vehicle no: SLN4593M HONDA VEZEL 1.5X A 17'

CHASSIS: RU11110262

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Distorted</i>		\$1,100.90	✓
2	2	Rear Boot Lid Hinges <i>3 new</i>	\$68.10	\$136.20	✓
3	2	Rear Boot Lid Shock Absorbers <i>new</i>	\$180.90	\$361.80	✓
4	1	Rear Boot Lid Emblem Logo <i>3 new</i>		\$45.10	✓
5	1	Rear Boot Lid Vezel Logo		\$56.30	✓
6	1	Rear Boot Lid Reverse Camera (Special Nett) <i>Damaged</i>		\$680.00 + 380(SN)	✓
7	1	Rear Boot Lid Number Plate <i>Best</i>		\$50.00	✓
8	1	Rear Boot Lid Emblem Top Garnish <i>included</i>		\$335.80	✓
9	2	Rear Boot Lid Side Reflector <i>at</i>	\$284.60	\$569.20	✓
10	1	Rear Boot Lid Lock <i>Damaged</i>		\$185.60	✓
11	1	Rear Boot Lid Weatherstrip <i>at</i>		\$135.25	✓
12	1	Rear Boot Lid Inner Trim Board <i>included</i>		\$355.75	✓
13	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$151.70	✓
14	2	Rear Boot Lid Windscreen Side Moulding <i>new</i>	\$75.00	\$150.00	✓
15	2	Rear Tail Lamp <i>LH included</i>	\$474.60	\$949.20 - 474.60	✓
16	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 8.00	✓
17	2	Rear Tail Lamp Lower Cover <i>LH torn</i>	\$198.70	\$397.40 198.70	✓
18	1	Rear Bumper <i>Deformed</i>		\$801.70	✓
19	2	Rear Bumper Side Retainer <i>new</i>	\$29.20	\$58.40	✓
20	2	Rear Bumper Side Reflector <i>LH included</i>	\$148.40	\$296.80 148.40	✓
21	1	Rear L/H Fender <i>Repair</i>		\$1,018.20	✓
22	1	Rear L/H Fender Cowling <i>3 new</i>		\$94.60	✓
23	8	Rear L/H Fender Cowling Clip <i>3 new</i>	\$6.50	\$52.00	✓
24	1	Rear L/H Fender Inner Trim Board <i>included</i>		\$325.25	✓
25	1	Rear L/H Fender Arch Protector <i>included</i>		\$125.00	✓
26	1	Rear End Panel <i>Distorted</i>		\$595.60	✓
27	1	Rear End Panel Top Garnish <i>Deformed</i>		\$122.30	✓
28	1	Rear End Panel Lock Sensor <i>included</i>		\$98.10	✓
29	1	Rear End Panel Buzzer <i>included</i>		\$94.00	✓

30	1	Rear End Panel Antenna Sensor	<i>3 Reported</i>	\$85.50	<i>x</i>
31	1	Rear End Panel Antenna Sensor Bracket		\$52.00	<i>x</i>
32	2	Rear Fender Inner Trim Board	<i>Reported</i>	\$325.25	<i>x</i>
33	8	Rear Fender Inner Trim Board Clip	<i>Nec</i>	\$6.50	<i>\$52.00 30</i>
34	1	Rear Spare Tyre Panel	<i>Buckled</i>	\$1,230.60	<i>✓ 1130</i>
35	1	Rear Spare Tyre Panel Top Cover	<i>Del'd</i>	\$306.65	<i>✓</i>
36	1	Rear Spare Tyre Panel Lower Cover	<i>Del'd</i>	\$190.90	<i>✓</i>
37	1	Rear Spare Tyre Panel Top Tool Box Sponge	<i>Crack'd</i>	\$285.45	<i>✓</i>
38	1	Rear Spare Tyre Panel & End Panel Sealant	<i>He re</i>	\$450.00	<i>x</i>

7949.25

Subtotal :- \$12,677.75

6359.40

380(SN)

Labour charges

To remove & refit cushion & trim board	\$280.00	<i>80</i>
To remove & refit reverse sensor	\$100.00	<i>50</i>
To remove & refit reverse camera	\$180.00	<i>50</i>
To remove & refit rear windscreen	\$120.00	<i>✓</i>
Gum	\$50.00	<i>✓</i>
To check wiring	\$100.00	<i>30</i>
Towing fee	\$100.00	<i>60 x</i>
Tuff kote	\$150.00	<i>60</i>
Panel beating	\$1,400.00	<i>1300</i>
Spray painting	\$1,400.00	<i>1900</i>

Subtotal :- \$3,880.00

Total:- \$16,557.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 9379.40

H/S: 7.5K

(7.5K)

Adrian G

H/S 23/03/21

09 Days.