



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO21003726/Uvf3n2 Date: 06/04/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 2798Z	Veh. Inspected	SKL 1209R
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2100897/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	23/03/2021
2. Vehicle Particulars & Condition			
Make & Model	BMW 316I (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WBA3A12080J721395	Colour	BROWN
Odometer	132601 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R18	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R18	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R18	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R18	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/03/2021	Inspection Date	24/03/2021
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	