


33	1 pc	Rear end panel inner <i>Regr</i>	-	-	598.40	+
34	1 pc	Rear end panel outer <i>Dented</i>	-	-	268.00	✓
35	1 pc	Rear tail-gate '70 KMPH' emblem	-	15.00	-	✓
36	1 pc	Rear tail-gate '5 PAX' emblem	-	15.00	-	✓
37	1 pc	Rear tail-gate 'NV200' emblem	-	-	78.50	✓
38	1 pc	Rear tail-gate 'NISSAN' emblem	-	-	81.40	✓
39	1 pc	Rear boot floor panel <i>Regr</i>	-	-	-	+
40	1 pc	Rear boot floor panel mat <i>New</i>	-	-	-	+
41	1 pc	Rear reverse sensor <i>Dented</i>	-	-280.00	-	200(SW)
42	1 pc	Rear regn. no plate <i>Regr</i>	-	-45.00	-	30(SW)
43	1 pc	Rear regn. no plate bracket <i>Regr</i>	-	29.00	-	✓
			Sub-Total:	0.00	1306.00	8,935.10
				30%	0%	10%
			After Less %:	0.00	1306.00	8,041.59
Labour						
1		To dismantle damaged parts, straighten & welding.	1,400.00	800		
2		To spray painting.	1,200.00	600		
3		To remove and replace rear o/s door <i>fitting</i>	100.00	60		
4		To remove and replace rear n/s door <i>fitting</i>	100.00	60		
5		To remove & refit rear o/s windscreen <i>2</i>	140.00	60		
6		To remove & refit rear n/s windscreen <i>2</i>	150.00	60		
7		To check wiring	80.00	30		
8		To re-seal anti-rust.	80.00	60		
			Sub-Total:	3,250.00		
			Total:	12,597.59		
			After Less 20%:	10,078.07		

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

*h/s 23/03/21
06 days.*



8778 1999
24 hr accident call



*Nett: 5266.60
Less 10%: 4739.94*

*S.N: 559
Labour: 1730*

*total: 7028.54
h/s: 5.61c.
06 Days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

GBB9414X ESTIMATEPg2