



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2200765

INV Date 14/02/2022

Reference CC4/LPC21003732/Kea3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SJF 7931S
Insured Veh. GBA 610K
Claim No. 20/21/21/VC05/024347
Policy No. Z20VC05005928
Accident Date 20/03/2021
Inspection Date 23/03/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21003732/Kea3q2 Date: 14/02/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 610K	Veh. Inspected	SJF 7931S	
Policy No.	Z20VC05005928	Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024347	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	23/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN LATIO (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JN1BAAC11Z0009322	Colour	WHITE	
Odometer	208249 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	MICHELIN	8 mm	
L/H Front Tyre	195/60 R15	MICHELIN	8 mm	
R/H Rear Tyre	195/60 R15	MICHELIN	8 mm	
L/H Rear Tyre	195/60 R15	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/03/2021	Inspection Date	23/03/2021	
Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 7931S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT (WCP)	BENT	280.00	280.00
1	REAR BOOT EMBLEM (WCP)	NECESSARY	40.00	40.00
1	REAR BOOT BADGE 'LATIO' (WCP)	NECESSARY	50.00	50.00
1	REAR BOOT CHROME MOULDING (WCP)	CRACKED	95.00	95.00
1	RH REAR BOOT HINGE (WCP)	TO REPAIR SEE LABOUR	55.00	-
1	LH REAR BOOT HINGE (WCP)	TO REPAIR SEE LABOUR	55.00	-
1	REAR BOOT SPOILER (WCP)	CRACKED	160.00	160.00
1	REAR BOOT INNER LOCK (WCP)	DENTED	125.00	125.00
1	REAR BOOT WEATHERSTRIP (WCP)	DISTORTED / DENTED	65.00	65.00
1	REAR BUMPER (WCP)	BUCKLED	260.00	260.00
1	SET REAR BUMPER CLIPS (WCP)	NECESSARY	16.00	16.00
1	REAR BUMPER SPOILER (WCP)	BUCKLED	280.00	280.00
1	REAR BUMPER SPOILER RUBBER SEAL (WCP)	NECESSARY	35.00	35.00
1	RH REAR BUMPER RETAINER (WCP)	DISTORTED	38.00	38.00
1	LH REAR BUMPER RETAINER (WCP)	DISTORTED	38.00	38.00
1	REAR END PANEL (WCP)	TO REPAIR SEE LABOUR	180.00	-
1	REAR END PANEL TOP TRIM (WCP)	DENTED	80.00	80.00
1	RH TAIL LAMP (WCP)	MTG CRACKED	110.00	110.00
1	LH TAIL LAMP (WCP)	MTG CRACKED	110.00	110.00
	COST PLUS 15%		310.80	267.30
			2,382.80	2,049.30
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	DENTED	45.00	45.00
1	REAR PARKING SENSOR (SN)	SHORTED	260.00	200.00
			305.00	245.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE REAR DAMAGED PARTS ,TO JACK OUT REAR END PANEL AND REAR FLOOR PANEL AND CUT OUT DAMAGED PANELS ,TO REWELD ,RESHAPE AND REPAIR LH AND RH REAR FENDER AND INNER PANEL,TO STRAIGHTEN OUT REAR CHASSIS MEMBER AND ADJUST REAR BODY AND BOOT ALIGNMENT.INCLUSIVE OF THE REPAIR OF RH REAR BOOT HINGE ,LH REAR BOOT HINGE AND REAR END PANEL.		680.00	650.00
	TO SPRAY PAINT REAR BUMPER ,REAR BOOT ,REAR END PANEL,LH & RH REAR FENDER,AFFECTED REAR AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIALS.		750.00	720.00
	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY .TO FOCUS HEADLAMP.		30.00	20.00
	TO APPLY ANTI-CORROSION TUFF-KOTE ON REWELDED SEAMS.		100.00	60.00
			1,560.00	1,450.00
GRAND TOTAL			4,247.80	3,744.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CC4/LPC21003732/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJF 7931S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJF 7931S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJF 7931S

RE-INSPECTION

