

|                  |               |
|------------------|---------------|
| Tax Invoice No.: | AR202106-0060 |
|------------------|---------------|

TSAO SU HUA @CINDY TSAO  
 NO. 141  
 JALAN BATALONG  
 SINGAPORE 509633

File No : SH/2021/025/03/006/TP  
 Date : 17-June-2021

**Cost of repair for vehicle no: SJF7931S NISSAN LATIO 1.5LT**  
**Accident involving vehicle no: SJF7931S & GBA610K on 20-March-2021**

**Description**

To Supply Spare Parts

To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out damaged panels, to reweld, reshape and repair LH and RH rear fender and inner panel, to straighten out rear chassis member and adjust rear body and boot alignment.  
 To spray paint rear bumper, rear boot, rear end panel, LH & RH rear fender, affected rear and inner damaged portion inclusive of preparatory works and materials.  
 To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.  
 To apply anti-corrosion Tuff-Kote on rewelded seams.

|                            |                 |
|----------------------------|-----------------|
| Lump Sum Cost of Repair \$ | 3,000.00        |
| 7% GST \$                  | 210.00          |
| <b>\$</b>                  | <b>3,210.00</b> |

T/Party: LONPAC INSURANCE BHD

**Received By**

No signature is required as this is a computer generated invoice