

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003738/BRA3Q2
Date: 10/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100469760
Claimant Vehicle No :	SMT848L	Insured Vehicle No :	GBF537M
Date of Loss:	21/03/2021	Nature of Claim:	TP
		Claim No:	2005518814SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT848L		
Make & Model:	MERCEDES-BENZ CLA180, 1.6 AMG (A)	Engine No:	28291480187925
Reg. Date:	26/03/2020 (Man. Year: 2019)	Chassis No:	WDD1183842N015000
Colour:	Red	Odometer:	19544 km
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,183.97	3,836.65	6,347.32	62.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	1,940.00	1,490.00	43.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,613.97	5,776.65	7,837.32	57.57
Approved Total (Overridden) (S\$)		4,600.00		

(S\$)	13,613.97	4,600.00	9,013.97	66.21
+ GST 7.00/7.00% (S\$)	952.98	322.00	630.98	66.21
Nett Amount (S\$)	14,566.95	4,922.00	9,644.95	66.21
+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$)		856.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,785.45		

INSPECTION

Date of Assignment: 23/03/2021

Date Inspected: 23/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

160 SIN MING DR #01-14

Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	2,553.80 FL	*1,870.00 FL
2	1		*FRONT DOOR INNER LOCK	Not Damaged	594.60 FL	*- FL
3	1		*FRONT DOOR INNER LOCK STRIKER	Not Damaged	68.00 FL	*- FL
4	1		*FRONT DOOR WEATHERSTRIP	Not Damaged	321.60 FL	*- FL
5	1		*FRONT DOOR OUTER HANDLE	Cut	498.00 FL	*389.50 FL
6	1		*FRONT DOOR OUTER MOULDING	Cut	368.70 FL	*285.00 FL
7	1		*FRONT DOOR FRAME RUBBER	Not Damaged	620.00 FL	*- FL
8	1		*FRONT DOOR INNER TRIM BOARD	Not Damaged	2,254.10 FL	*- FL
9	1		*FRONT DOOR REGULATOR	Not Damaged	350.00 FL	*- FL
10	1		*FRONT DOOR REGULATOR MOTOR	Not Damaged	488.00 FL	*- FL
11	1		*SIDE SKIRT RH	Not Damaged	689.00 FL	*- FL
12	1		*SIDE MIRROR ASSY RH	Cut	987.50 FL	*774.00 FL
13	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
14	1		*FRONT DOOR SEALANT	Necessary	100.00 FS	*60.00 FS
15	1		*FRONT DOOR INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
16	1		*FRONT DOOR SPEAKER	Not Damaged	210.00 FS	*- FS
17	1		*FRONT DOOR WRAP STICKER	Necessary	550.00 FS	*550.00 FS
18	1		*SIDE SKIRT CLIPS	Not Necessary	60.00 FS	*- FS
19	1		*SIDE MIRROR SEAL	Necessary	60.00 FS	*30.00 FS
20	1		*SIDE MIRROR WRAP STICKER	Necessary	250.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,163.30	4,168.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	979.33	331.85
Total Parts (\$\$)	10,183.97	3,836.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R FRONT DOOR COMPONENT	New	150.00	100.00
2	UPHOLSTERY	New	200.00	0.00
3	CHECK WIRING	New	100.00	60.00
4	CONDUCT WATER LEAK TEST	New	180.00	0.00
5	DIAGNOSTIC RESET FAULT CODE	New	300.00	120.00
6	COATING	New	800.00	600.00
7	PANEL BEATING	New	800.00	600.00
8	RUST PROOFING	New	100.00	60.00
9	SPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (\$\$)			3,430.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >