


ASS. REC. BY: 628

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Bifrost Auto
 of _____
 Insured: _____
 Policy No. _____
 Claims No. C10009319/KY
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 28 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SUC8716R Yr Regn: 02 Feb 2017
 Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Vezel 1.5X c.c. 1496
 Colour: Brown A/C: Insured / Std / NI / NA
 Sp. Reading: 59332 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RU11206349
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 24-03-21
 Survey held at W/S 10:45
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 23/07/21@12.58pm Guo Qiang finalised with Suanne LS \$3100, 4 days. (Red \$12946.66, 81%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 27/07 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Misc (\$

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Other:

TP

3100

Estimate for SLK8716R(Honda Vezel)

1 *TAILGATE	/ Ruc		\$1,542.00
1 *TAILGATE OUTER GARNISH	X	NN	\$421.00
2 *TAILGATE REFLECTOR	X		\$842.20
1 *TAILGATE INNER TRIM	/ CFA		\$358.00
1 *TAILGATE GLASS MOULDING	/ MBL		\$672.00
1 *TAILGATE INNER HANDLE	/ CFA		\$68.50
1 *TAILGATE LOCK	/ CFA		\$224.00
1 *TAILGATE LOWER LOCK	X	NN	\$24.00
1 *TAILGATE WEATHERSTRIP	/ Tui		\$154.00
1 *TAILGATE WIPER MOTOR	X	NN	\$541.00
1 *TAILGATE LOGO	X		\$84.00
1 *TAILGATE EMBLEM VEZEL	/ MBL		\$56.00
1 *TAILGATE STOPPER	X	NN	\$36.00
1 *TAILGATE DETECTOR	X		\$321.00
1 *TAILGATE BUZZER	/ DM		\$125.00
2 *TAIL LAMP	X	NN	\$920.00
1 *REAR BUMPER	/ Re		\$689.00
2 *REAR BUMPER SIDE UPPER	X		\$900.00
2 *REAR BUMPER SIDE RETAINER	X		\$110.00
2 *REAR BUMPER REFLECTOR	X	NN	\$90.00
2 *REAR FENDER INNER COWLING	X		\$374.00
2 *REAR WHEEL ARCH GARNISH	X		\$624.00
2 *REAR FENDER INNER TRIM	X		\$1,096.00
1 *REAR END PANEL	X repair		\$630.00
1 *REAR END PANEL TOP GARNISH	/ CFA		\$189.00
*REAR FLOOR PANEL	X repair		\$845.00
*REAR FLOOR PANEL TOP BOARD	X		\$300.00
*REAR FLOOR PANEL UNDER COVER	X	NN	\$254.00
*REAR FLOOR PANEL TOOLS BOX SPONGE	X		\$258.00
			\$12,747.70
Less 20%			\$2,549.54
			\$10,198.16

10 *REAR BUMPER CLIPS	/ NEC NEC		\$65.00
10 *REAR BUMPER SIDE UPPER CLIP	X	NN	\$39.00
1 *TAILGATE SEALANT	X		\$80.00
10 *TAILGATE INNER TRIM CLIP	/	NN	\$78.00
1 *TAILGATE WINDSCREEN SEALANT	/		\$80.00
1 *TAILGATE WINDSCREEN INNER SEAL	X		\$50.00
4 *TAIL LAMP CLIP	X	NN	\$32.00
10 *REAR FENDER INNER COWLING CLIP	X		\$97.50
10 *REAR FENDER INNER TRIM CLIP	X		\$78.00

10 *REAR WHEEL ARCH GARNISH CLIP	X ^{MM}	\$65.00
10 *REAR END PANEL TOP GARNISH CLIPS	/ ^{MC}	\$34.00
1 *REAR END PANEL INSULATION SEAL	X { ^{NN}	\$150.00
1 *REAR FLOOR PANEL INSULATION SEAL	X { ^{NN}	\$150.00
1 *REVERSE SENSOR	✓ ^{PM}	\$300.00 200
1 *REVERSE CAMERA	X ^{NN}	\$450.00
		<u>\$1,748.50</u>

TO PANEL BEAT, REMOVE AND REPLACE PARTS

\$1,400.00 ~~400~~ 500

TO SPRAY PAINT AFFECTED AREA

\$1,400.00 400

WIRING CHECK

\$60.00 30

REMOVE AND REFIX REAR WINDSCREEN

\$150.00 100

CONDUCT LEAKAGE TEST ON TAILGATE

\$80.00 X

TUFF COAT

\$250.00 X { ^{NN}

REMOVE AND REFIX EXHAUST TAILPIPE

\$280.00 X

REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY TO FACILITATE REPAIR

\$200.00 60

REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING

\$280.00 40.

\$4,100.00

Total

\$16,046.66

4 Days.
 Complete Repair
 After repair photos
 Gene Q. R. P.
 24/3/21.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: