

Estimate for SLK8716R(Honda Vezel)

1 *TAILGATE	/ Ruc		\$1,542.00	1100
1 *TAILGATE OUTER GARNISH	X	NN	\$421.00	
2 *TAILGATE REFLECTOR	X		\$842.20	
1 *TAILGATE INNER TRIM	/ CFA		\$358.00	✓
1 *TAILGATE GLASS MOULDING	/ MBL		\$672.00	145
1 *TAILGATE INNER HANDLE	/ CFA		\$68.50	✓
1 *TAILGATE LOCK	/ CFA		\$224.00	✓
1 *TAILGATE LOWER LOCK	X	NN	\$24.00	
1 *TAILGATE WEATHERSTRIP	/ Tui		\$154.00	✓
1 *TAILGATE WIPER MOTOR	X	NN	\$541.00	
1 *TAILGATE LOGO	X		\$84.00	
1 *TAILGATE EMBLEM VEZEL	/ MBL		\$56.00	✓
1 *TAILGATE STOPPER	X	NN	\$36.00	
1 *TAILGATE DETECTOR	X		\$321.00	
1 *TAILGATE BUZZER	/ DM		\$125.00	109
2 *TAIL LAMP	X	NN	\$920.00	
1 *REAR BUMPER	/ Re		\$689.00	✓
2 *REAR BUMPER SIDE UPPER	X		\$900.00	
2 *REAR BUMPER SIDE RETAINER	X		\$110.00	
2 *REAR BUMPER REFLECTOR	X	NN	\$90.00	
2 *REAR FENDER INNER COWLING	X		\$374.00	
2 *REAR WHEEL ARCH GARNISH	X		\$624.00	
2 *REAR FENDER INNER TRIM	X		\$1,096.00	
1 *REAR END PANEL	X repair		\$630.00	
1 *REAR END PANEL TOP GARNISH	/ CFA		\$189.00	136.5
*REAR FLOOR PANEL	X repair		\$845.00	
*REAR FLOOR PANEL TOP BOARD	X		\$300.00	
*REAR FLOOR PANEL UNDER COVER	X	NN	\$254.00	
*REAR FLOOR PANEL TOOLS BOX SPONGE	X		\$258.00	
			\$12,747.70	3040
Less 20%			\$2,549.54	
			\$10,198.16	2432

10 *REAR BUMPER CLIPS	/ NEC NEC		\$65.00	30
10 *REAR BUMPER SIDE UPPER CLIP	X	NN	\$39.00	
1 *TAILGATE SEALANT	X		\$80.00	
10 *TAILGATE INNER TRIM CLIP	/	NN	\$78.00	30
1 *TAILGATE WINDSCREEN SEALANT	/		\$80.00	40
1 *TAILGATE WINDSCREEN INNER SEAL	X		\$50.00	
4 *TAIL LAMP CLIP	X	NN	\$32.00	
10 *REAR FENDER INNER COWLING CLIP	X		\$97.50	
10 *REAR FENDER INNER TRIM CLIP	X		\$78.00	

10 *REAR WHEEL ARCH GARNISH CLIP	X <i>MV</i>	\$65.00	
10 *REAR END PANEL TOP GARNISH CLIPS	<i>MC</i>	\$34.00	10
1 *REAR END PANEL INSULATION SEAL	X <i>{ NN</i>	\$150.00	
1 *REAR FLOOR PANEL INSULATION SEAL	X <i>{ NN</i>	\$150.00	
1 *REVERSE SENSOR	<i>✓ PM</i>	\$300.00	200
1 *REVERSE CAMERA	X <i>NN</i>	\$450.00	
		<u>\$1,748.50</u>	310

TO PANEL BEAT, REMOVE AND REPLACE PARTS

TO SPRAY PAINT AFFECTED AREA

WIRING CHECK

REMOVE AND REFIX REAR WINDSCREEN

CONDUCT LEAKAGE TEST ON TAILGATE

TUFF COAT

REMOVE AND REFIX EXHAUST TAILPIPE

REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY TO FACILITATE REPAIR

REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING

\$1,400.00	<i>400 500</i>
\$1,400.00	<i>400</i>
\$60.00	<i>30</i>
\$150.00	<i>100</i>
\$80.00	<i>X</i>
\$250.00	<i>X { NN</i>
\$280.00	<i>X</i>
\$200.00	<i>60</i>
\$280.00	<i>40</i>
<u>\$4,100.00</u>	1130

Total

\$16,046.66 3872

-20%: 3100

*4 Days -
Complete Repair
After repair photos
Gino Ricci
24/3/21*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: