

COMFORTDELGRO ENGINEERING PTE LTD

Date: 23.03.2021

REPAIR ESTIMATE

Time: 08:15:15

Page: 1

Fig Asia CP/P

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305460023

REGN NO : SHB2888L

MILEAGE : 0000000000

MAKE : HYUNDAI

MODEL : IONIQ(G3)

DATE OF REGN : 30.10.2020

DATE/TIME IN : 22.03.2021 15:10

ACCIDENT DATE : 22.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 03-01-0104-2061-G REAR WHEEL CAP RH 1 346.40 20.00 277.12 *ent*0002 28-01-9999-2024-A REAR DR APPS STICKER RH 1 80.00 80.00 *ver*

SUB-TOTAL : 357.12 ✓

## JOB NATURE

0000 PB PANEL BEATING-Rear Fender RH 400.00 *350*0001 SP Spraypaint-Rr Bumper&Rocker Pnl etc 1200.00 *850*SUB-TOTAL : 1,600.00 *1200*

TOTAL : 1,957.12

MVA NAME &amp; SIGNATURE

DATE :

AUTHORISED : YES / NO

DATE :

SURVEYOR NAME &amp; SIGNATURE

\$1557.12

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanglin 23/2/21 @ 12pm

2 days

p/p Repair after repair  
Tanglin @ LKK auto