



1st Auto Pro Pte Ltd

We Believe In Service

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-49 & #01-51/52 SINGAPORE 415875

Tel : 9188 3197 / 8614 6767 | Email: christina@1ap.com.sg

ESTIMATION QUOTE

CHINA TAIPING INSURANCE (SG) PTE LTD

3 ANSON ROAD #15-00

SPRINGLEAF TOWER

SINGAPORE 79909

ATTN: MOTOR CLAIMS DEPARTMENT

Denise.

KMH DU41BR9u

VEHICLE NO : SJP5243E

MAKE MODEL : HYUNDAI AVNATE

REFERENCE : 1AP-202103-10

DOA : 15-Mar-21

CLAIM TYPE : TP CLAIM

PAGE 1 OF 3

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
*BONNET	1	\$ 1,021.20	X
*BONNET HINGE LH / RH	2	\$ 216.00	X
*BONNET INSULATOR	1	\$ 215.00	X
*BONNET LOCK	1	\$ 198.70	X
*BONNET LOCK COVER	1	\$ 154.00	X
*BONNET WEATHERSTRIP	1	\$ 131.90	X
*FRONT BUMPER	1	\$ 598.00	A78
*FRONT BUMPER LOWER GRILLE	1	\$ 267.50	105
*FRONT BUMPER FOGLAMP COVER LH / RH	2	\$ 492.00	X
*FRONT BUMPER SIDE RETAINER LH / RH	2	\$ 220.00	75
*FRONT BUMPER REINFORCEMENT	1	\$ 589.00	254
*FRONT BUMPER SPONGE	1	\$ 316.40	118
*FRONT FENDER INNER COWLING LH / RH	2	\$ 390.80	X
*HEAD LAMP LH / RH	2	\$ 1,856.00	1164
*HEAD LAMP LOWER BRACKET LH / RH	2	\$ 338.80	X
*FRONT SUPPORT PANEL	1	\$ 865.00	X
*FRONT SUPPORT PANEL UNDER COVER	1	\$ 256.00	X
*REAR BUMPER	1	\$ 644.00	495
*REAR BUMPER RETAINER LH / RH	2	\$ 334.00	70
*REAR BUMPER BRACKET LH / RH	2	\$ 340.00	X
*REAR BUMPER REINFORCEMENT	1	\$ 454.00	282
*REAR BUMPER REINFORCEMENT BRACKET LH / RH	2	\$ 312.00	125
*REAR BUMPER SPONGE	1	\$ 310.00	119
*REAR WINDSCREEN MOULDING	1	\$ 218.00	X
*BOOTLID	1	\$ 985.90	X
*BOOTLID EMBLEM AVANTE	1	\$ 156.00	52
*BOOTLID EMBLEM S	1	\$ 117.00	48
*BOOTLID REFLECTOR LH / RH	2	\$ 980.00	241
*BOOTLID NUMBER PLATE LAMP	1	\$ 124.20	X
*BOOTLID HINGE LH / RH	2	\$ 528.00	X
*BOOTLID STOPPER LH / RH	2	\$ 272.40	X
*BOOTLID INNER TRIM	1	\$ 384.00	X

ESTIMATION QUOTE

CHINA TAIPING INSURANCE (SG) PTE LTD
3 ANSON ROAD #15-00
SPRINGLEAF TOWER
SINGAPORE 79909
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SJP5243E
MAKE MODEL : HYUNDAI AVNATE
REFERENCE : 1AP-202103-10
DOA : 15-Mar-21
CLAIM TYPE : TP CLAIM

PAGE 2 OF 3

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
*BOOTLID LOGO <i>new</i>	1	\$ 137.40	39.
*BOOTLID TOP LOCK <i>Damaged</i>	1	\$ 248.00	158.
*BOOTLID LOWER LOCK <i>new</i>	1	\$ 142.70	X
*BOOTLID WEATHERSTRIP <i>cut</i>	1	\$ 321.00	165
*TAILLAMP LH / RH <i>RH cracked</i>	2	\$ 1,616.00	287.
*TAILLAMP PANEL LH / RH <i>RH Dented</i>	2	\$ 1,156.00	175
*REAR FENDER INNER COWLING LH / RH <i>7 up</i>	2	\$ 394.80	X
*REAR FENDER INNER TRIM LH / RH <i>RH torn</i>	2	\$ 978.00	X 245.
*REAR END PANEL <i>Dented</i>	1	\$ 780.00	485
*REAR END PANEL TOP GARNISH <i>cracked</i>	1	\$ 245.00	86.
*REAR FLOOR PANEL <i>Repair</i>	1	\$ 986.90	X
*REAR FLOOR PANEL TOP BOARD <i>torn</i>	1	\$ 286.40	✓
*REAR FLOOR PANEL TOOLS BOX <i>new</i>	1	\$ 287.40	X.
*REAR EXHAUST PIPE <i>Repair</i>	1	\$ 965.00	X

\$ 22,830.40
6538.3 LESS 20% \$ 4,566.08
5230.64 SUBTOTAL \$ 18,264.32
BALANCE C/F \$ 18,264.32

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 18,264.32	
*FRONT NUMBER PLATE <i>Dented</i>	1	\$ 100.00	50
*FRONT BUMPER CLIP <i>new</i>	1	\$ 50.00	30
*BONNET SEALANT <i>new</i>	1	\$ 80.00	X
*BONNET INSULATOR CLIP <i>3 up</i>	1	\$ 50.00	X
*FRONT FENDER INNER COWLING CLIP <i>3 up</i>	1	\$ 50.00	X
*REAR NUMBER PLATE <i>new</i>	1	\$ 100.00	X
*REAR BUMPER CLIP <i>new</i>	1	\$ 50.00	30
*REAR WINDSCREEN SEALANT <i>3</i>	1	\$ 150.00	X
*BOOT LID SEALANT <i>new</i>	1	\$ 80.00	X
*BOOT LID INSULATOR CLIP <i>new</i>	1	\$ 50.00	X
*BOOTLID OUTER MOULDING CLIP <i>new</i>	1	\$ 50.00	X
*TAIL LAMP CLIP <i>new</i>	1	\$ 50.00	10
*TAIL LAMP PANEL SEALANT <i>new</i>	1	\$ 160.00	X
*REAR FENDER INNER COWLING CLIP <i>new</i>	1	\$ 50.00	X
*REAR FENDER INNER TRIM CLIPS <i>new</i>	1	\$ 50.00	30
*REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1	\$ 50.00	10.
*REAR END PANEL SEALANT <i>new</i>	1	\$ 120.00	60
*REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 250.00	X
*REVERSE SENSOR <i>Damaged</i>	1 SET	\$ 220.00	200

SUBTOTAL \$ 1,760.00
BALANCE C/F \$ 20,024.32

420

ESTIMATION QUOTE

CHINA TAIPING INSURANCE (SG) PTE LTD

3 ANSON ROAD #15-00

SPRINGLEAF TOWER

SINGAPORE 79909

ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SJP5243E

MAKE MODEL : HYUNDAI AVNATE

REFERENCE : 1AP-202103-10

DOA : 15-Mar-21

CLAIM TYPE : TP CLAIM

PAGE 3 OF 3

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F \$ 20,024.32			
TO REMOVE, REFIT AND TRANSFER FRONT BUMPER + REAR BOOT COMPONENT	1	\$ 300.00	X.
TO REMOVE AND REFIT ELECTRICAL WIRING, REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING - FRONT + REAR	2	\$ 300.00	60
TO REMOVE AND REFIT INNER TRIMS AND GARNISHES TO FACILITATE THE REPAIR - FRONT + REAR	3	\$ 300.00	80
TO REMOVE AND REFIT REAR BUMPER SENSOR	4	\$ 100.00	50
TO REMOVE AND REFIT REAR WINDSCREEN	5	\$ 200.00	X.
TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTING	6	\$ 350.00	X.
TO APPLY UNDERCOATING ON REPLACED AND REPAIRED PANELS FOR RUST PROTECTION	7	\$ 100.00	60
TO PROVIDE SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS	8	\$ 3,000.00	1000.
TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO ORIGINAL POSITION USING POWER TOOLS	1	\$ 3,000.00	1100.

SUBTOTAL \$ 7,650.00

GRAND TOTAL \$ 27,674.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2350

total: 8000.64

2/s: 6.4K

09 Days