

Mr HSIANG TONG

Date : 23-Mar-21

Registration no. : SLP4546P / Mazda 5 5-Dr Wagon 2.0L SP.6EAT Sunroof
DOA : 22-Mar-21 Estimate No. : 19A051_SLP4546P_MAZDA5

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Rear sliding door RH	1859.80 ✓
2	1	Rocker panel garnish RH <i>Body ID / Sun</i>	1859.80 ✓
3	1	Rear sliding door weatherstrip RH	392.20 X
4	1	Rear sliding door lower roller RH	184.00 X
5	1	Rear sliding door centre roller RH	195.00 X
6	1	Rear fender RH	1295.60 ✓
7	1	Rear fender inner shield RH	124.00 X
8	1	Rear fender glass moulding RH	109.00 X
9	1	Taillamp RH	476.00 X
10	1	Rear shock absorber RH	200.80 X
11	1	Rear lower arm RH	326.60 ✓
12	1	Rear upper arm RH	188.40 X
13	1	Rear lateral arm RH	138.50 ✓
14	1	Rear trailing arm RH	603.30 ✓
15	1	Rear wheel bearing RH	215.00 ✓
16	1	Rear bumper	879.00 ✓
17	1	Rear bumper side retainer RH	102.00 ✓
			7289.20

not Authorised
23/3/21
highlight the sign
1/5 \$ 6200
6 days

Less 10% 20%

728.92
6560.28

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-606330
202
P-48064
S/W-720
L-2280
785064
22
6280

Date : 23-Mar-21

Registration no. : SLP4546P / Mazda 5 5-Dr Wagon 2.0L SP.6EAT Sunroof

DOA : 22-Mar-21

Estimate No. : 19A051_SLP4546P_MAZDA5

S/N	Qty	Item	Amount
-----	-----	------	--------

SPECIAL NETT ITEMS

1	1	Sundries	17	60.00	X
2	1set	Rear sliding door trimboard clips RH	neu	50.00	✓
3	1	Rear sliding door sealant RH	17	100.00	X
4	1set	Rear fender inner shield clips RH	17	40.00	X
5	1set	Rear fender inner garnish clips RH	17	60.00	X
6	1	Rear fender glass primer and cleaner RH	17	100.00	X
7	1	Rear fender glass inner seal RH	neu	100.00	30
8	1	Rear fender glass sealant RH	neu	100.00	40
9	1	Rear alloy rim RH	neu	650.00	550
10	1	Rear tyre RH	neu	280.00	X
11	1set	Rear bumper clips	neu	80.00	50
				1620.00	
Parts Total				8180.28	720

LABOUR & MISC CHARGES

1	1	Panel beating and strenghten parts on accident area.		1600.00	800
2	1	Check wiring system after disconnect and connect.		80.00	20
3	1	R&R interior upholstery.		200.00	80
3	1	R&R RH rear sliding door component.		100.00	60
4	1	R&R RH rear fender glass.		180.00	100
5	1	R&R RH rear sliding door component.	Repeat	100.00	X
6	1	R&R RH rear undercarriage.		280.00	120
7	1	R&R RH rear tyre and balancing	17	80.00	X
8	1	R&R fuel tank.		350.00	60
8	1	To conduct wheel alignment.		120.00	80
9	1	To apply undercoating for rust roofing.		200.00	60
10	1	Spray painting on accident area.		1200.00	900
Labour Total				4490.00	

Total Parts and Labour Cost of Repair				12670.28	720
--	--	--	--	----------	-----