

Section A - Accident Details	
Registration Number	SHD6093B
Case Reference Number	TAX/03/21/2057
Registration Date	27/7/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	RUSLI BIN SHAHDAN
Type of Accident	Head to Rear
Accident Date and Time	17/3/2021 9:30 AM
Accident Reported Date and Time	18/3/2021 2:59 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110134
Special Instruction to ARC, if any	TP / REAR PORTION / AIG - LKK
Prepared Date and Time	19/3/2021 9:52 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$1,296.00	\$400.00
Total Spare Part Cost	\$5,453.86	\$1,397.65
Total Other Cost	\$720.00	\$250.00
TOTAL COST	\$8,145.86	\$2,447.65
Lump Sum Total	\$8,150.00	\$2,450.00 (L/S)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	22/03/2021 5:39 PM	22/03/2021 11:28 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP = 0 day	L/S, after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2104-0051	Invoice Number	
Quotation Date	08.04.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$676.00	\$400.00 ✓
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00 ✓
Total Spray Painting & Panel Beating	\$1,296.00	\$400.00 ✓

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00 ✓
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$50.00 ✓
TO REMOVE AND REFIX TAILGATE GLASS	\$120.00	\$100.00 ✓
TO REMOVE AND REFIX REAR WINDSCREEN	\$120.00	\$60.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$720.00	\$250.00 ✓

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace ✓
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace ✓
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check X
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		89997-30070	ANTENNA,ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check X
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace ✓
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given X
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given X

CRU
Nec
Nec
SVC
SVC
SVC
SVC
short
SVC

	76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Check	X
	76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Check	X
	76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Check	X
	58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Check	X
	51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Check	X
	58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check	X
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace	X
	75574-47020	TAILGATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	X
	75574-47020	TAILGATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	X
	68105-47122	TAILGATE DOOR GLASS	0.00	\$1,090.90	0.00	\$0.00	Replace	Not Given	X
	75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace	X
	64821-47030	TAILGATE LOWER WINDOW GLASS	0.00	\$721.30	0.00	\$0.00	Replace	Not Given	X
		SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	X
	76085-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given	X
	81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Not Given	X
	81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Not Given	X
Total				\$8,329.10		\$1,592.78			

} SVC
 DD
 Nec
 Nec
 SVC
 Nec
 SVC
 Nec
 } SVC

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
Total					205.70		154.28		

BT

1747.06 /
 - 208

 1397.65 /
 + 400.00 /
 + 650.00 /

 2447.65 /
 45 \$2,450 /
 3 days

SHD 6093B