



S THREE AUTOMOTIVE RECOVERY PTE LTD

MOTOR CLAIM DEPT.

T/P VEH. NO. : SHC7450C

ESTIMATE REPORT 1st QUOTATION

OWNER'S PARTICULAR

NAME : HO CHING PENG
ADDRESS : 12A LORNE ROAD
SINGAPORE 298896
LICENSE NO. : SFF2345P TRANS.
MAKE / MODEL : MERCEDES S300L
OWNER'S INSURER : AIG
JOB-CODE : TP S/A : JOEY

JOB NO. :

CONTACT :

CHASSIS NO. :

ENGINE NO. :

ACCIDENT DATE : 19-Mar-21

Not Authorised
11 Sep 83750h
Recovery After Rain
3 days

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR. DISP	REV. PRICE
1 REAR BOOTLID	1.00	3100.00	10.00	2790.00	Y	X
2 REAR BOOTLID S300 EMBLEM	1.00	75.00	10.00	67.50	Y	X
3 REAR BOOTLID LOGO	1.00	78.00	10.00	70.20	Y	X
4 REAR BOOTLID 7G TRONIC EMBLEM	1.00	122.00	10.00	109.80	Y	X
5 REAR BOOTLID INNER LOCK MECHANISM	1.00	780.00	10.00	702.00	Y	X
6 REAR BOOTLID CATCH	1.00	232.00	10.00	208.80	Y	X
7 REAR BOOTLID WEATHERSTRIP	1.00	228.00	10.00	205.20	Y	X
8 REAR BOOTLID INNER TRIM	1.00	620.00	10.00	558.00	Y	X
9 REAR BOOTLID CHROME MOULDING	1.00	580.00	10.00	522.00	Y	X
10 REAR BOOTLID SIDE GARNISH INNER RH	1.00	176.00	10.00	158.40	Y	X
11 REAR BUMPER 1840	1.00	2100.00	10.00	1890.00	Y	✓
12 REAR BUMPER SIDE RETAINER LH	1.00	148.00	10.00	133.20	Y	X
REAR BUMPER SIDE RETAINER RH 120	1.00	148.00	10.00	133.20	Y	2
REAR BUMPER REINFORCEMENT BEAM 650	1.00	986.00	10.00	887.40	Y	2
REAR BUMPER REINFORCEMENT BRACKET	1.00	376.00	10.00	338.40	Y	X
REAR BUMPER TOW COVER	1.00	48.00	10.00	43.20	Y	X
REAR BUMPER INNER PLASTIC BEAM	1.00	832.00	10.00	748.80	Y	X
TAILLAMP RH P-7 650	1.00	2140.00	10.00	1926.00	Y	✓
TAILLAMP BRACKET RH	1.00	680.00	10.00	612.00	Y	X
TAILLAMP MOULDING RH	1.00	320.00	10.00	288.00	Y	X
REAR END PANEL	1.00	1039.00	10.00	935.10	Y	X
REAR END PANEL TOP GARNISH	1.00	265.00	10.00	238.50	Y	X
REAR EXHAUST SHIELD 235	1.00	283.00	10.00	254.70	Y	2
REAR SPARE TYRE FIBRE PANEL	1.00	1080.00	10.00	972.00	Y	X
KEYLESS SENSOR	1.00	380.00	10.00	342.00	Y	X
TOTAL (PARTS) :		16816.00		15134.40		

NETT ITEM

REAR BUMPER CLIPS	1.00	80.00	0.00	80.00	Y	50.00
REVERSE SENSOR WITH HOLDERS P-7 260	1.00	1200.00	0.00	1200.00	Y	2
REVERSE SENSOR WIRE HARNESS 250	1.00	790.00	0.00	790.00	Y	X
REAR END PANEL SEALANT	1.00	100.00	0.00	100.00	Y	X

Faster
memory
speedPrecision
touchpadFaster
wirelessGigab
Ether

• Intel® Celeron® processor N4020

• Intel® UHD Graphics

• 4 GB DDR4 Memory

• 128GB SSD

ARE TYRE PANEL SEALANT
K BOOTLID INNER TRIM CLIPS

1.00	280.00	0.00	280.00	Y	X
1.00	80.00	0.00	80.00	Y	X

TOTAL (PARTS) :

2530.00 2530.00

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	1.00	1200.00	0.00	1200.00	Y	2501
2	SPRAY PAINTING ON ACCIDENT AREA	1.00	1200.00	0.00	1200.00	Y	481
3	CHECK & REPAIR WIRING SYSTEM	1.00	150.00	0.00	150.00	Y	201
4	R&R BOOTLID COMPARTMENT	1.00	150.00	0.00	150.00	Y	X
5	RESET BOOTLID LOCK MECHANISM	1.00	150.00	0.00	150.00	Y	X
6	R&R EXHAUST HEATSHIELD SYSTEM	1.00	150.00	0.00	150.00	Y	301
7	RESPRAY TUFF KOTE ON AFFECTED AREA	1.00	150.00	0.00	150.00	Y	X
8	R&R REVERSE SENSOR & RESETTING OF SYSTEM	1.00	380.00	0.00	380.00	Y	X

TOTAL (LABOUR) :

3530.00 3530.00

TOTAL PARTS & LABOUR

22876.00 21194.40

CESS : : \$

OF DAY : 8-3 days

SURVEY : BEFORE / AFTER PAINTING ✓

T-BY PART OR LUMP-SUM : \$

E OF SURVEY : 23/3/21

VEY BY : Kenneth

FACT NO :

FAX NO :

: LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



S THREE AUTOMOTIVE RECOVERY PTE LTD

ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO : SHC7450C

ESTIMATE REPORT 1st QUOTATION

JOB NO : _____

OWNER'S PARTICULAR

NAME : HO CHING PENG
ADDRESS : 12A LORNIE ROAD
SINGAPORE 298696
LICENSE NO. : SFF2345P TRANS.
MAKE / MODEL : MERCEDES S300L
OWNER'S INSURER : AIG
JOB-CODE : TP S/A : JOEY

CONTACT :

CHASSIS NO :

ENGINE NO :

ACCIDENT DATE : 19-Mar-21

SUPPLYMENTARY

1	REAR BUMPER LOWER BRACKET LH	1.00	CM	90.00	10.00	81.00	Y	<u> </u>
2	REAR BUMPER LOWER BRACKET RH	1.00	CM	90.00	10.00	81.00	Y	<u> </u>
3	TAILLAMP SIDE GARNISH COVER RH	1.00	DI	85.00	10.00	76.50	Y	<u> </u>

ACCESS : : S\$ _____

D. OF DAY : _____

-SURVEY : BEFORE / AFTER PAINTING

RT-BY-PART OR LUMP-SUM : S\$ _____

TE OF SURVEY : ____/____/____

VEY BY : _____

TACT NO : _____

FAX NO : _____

E : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.