

# Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225  
H/P 91082728

Tan Tong Lim  
Blk 163B Rivervale Crescent  
#06-252  
Singapore 542163

Vehicle No : SLH 6705 B  
Make/Model : Honda Shuttle  
Year : 2017

*Not Notwithstanding  
L1Png B395de  
Purning After Pain*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy	By \$1,193.70	—
1 pc	Rear tail-gate glass moulding	na \$105.20	—
1 pc	Rear tail-gate emblem " Shuttle "	na \$65.10	—
1 pc	Rear tail-gate emblem " Hybrid "	na \$57.20	—
1 pc	Rear tail-gate outer garnish	in \$385.70	X
1 pc	Rear tail-gate inner lock	na \$207.80	—
1 pc	Rear tail-gate inner trim board	na \$287.40	—
2 pcs	Rear fender inner trim board	na \$797.20	X
1 pc	Rear boot rubber	na \$195.70	50% na
1 pc	Rear end panel <i>546.70</i>	By \$588.60	—
1 pc	Rear end panel inner garnish <i>Pr:</i>	na \$185.40	—
1 pc	Rear bumper	na \$465.70	—
2 pcs	Rear bumper side retainer	\$38.20 in	\$76.40 X
2 pcs	Rear bumper reflector	\$155.20 in	\$310.40 X
2 pcs	Rear bumper reflector garnish	\$106.70 in	\$213.40 X
2 pcs	Rear bumper reflector inner sponge	disc \$87.10 in	\$164.20 X
1 pc	Rear antenna	in	\$125.60 X
			\$6,573.00 5934.70
Less 20 %			\$1,314.60
			\$5,258.40 4747.76

S Nett

1 pc	Rear tail-gate glass sealant	na \$55.00	40% na
20 pcs	Rear bumper clip	\$2.00 na	\$40.00 —
1 pc	Rear reverse sensor	in	\$200.00 X
			\$295.00

balance c/f

\$5,553.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

SLH 6705 B

balance b/f \$5,553.40

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$1,200.00	<i>bol</i>
To putty and spray paint	\$1,200.00	<i>bol</i>
Check & reconnect wiring.	\$45.00	<i>bol</i>
To respray anti-rust proofing treatment	\$120.00	<i>bol</i>
Remove/refit rear windscreen to facilitate repair	\$100.00	<i>✓</i>
Remove/refit rear tail-gate mechanism to new door.	\$150.00	<i>bol</i>
Remove/refit rear boot upholstery to facilitate repair.	\$100.00	<i>bol</i>
Total	<u>\$8,468.40</u>	7957.76