

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD106M**AAD2103-115***Not Authorised*
L/Smp B

Vehicle No.:
 Chassis No.: **23 MAR 2021**
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD106M
VF1ABL15AUC282174
RENAULT
LATITUDE
22/03/2021
III
14/08/2015

PART	LIST
1 BUMPER COVER FRT	\$ Bu 747.20 —
1 BUMPER ABSORBER FRT	\$ Su 394.68 X
1 BUMPER BEAM FRT	\$ R 663.70 X
1 BUMPER BRACKET KIT FRT RH	\$ Div 101.40 —
1 FENDER PANEL FRT RH	\$ R 437.10 —
1 WHEELARCH FRT RH	\$ Cm 191.40 —
1 HEADLAMP RH	\$ mgcm 743.60 —
1 BUMPER FOG LAMP GRILLE RH	\$ nll 207.21 —
1 WIPER RESERVOIR	\$ R 179.60 X
	\$ 3,665.89
	10% \$ 366.59
	\$ 3,299.30

Special Nett	
1SET BUMPER BRACKET CTR CLIP	\$ na na 33.00 X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$ na 10.00 X
1SET BUMPER RETAINER RH CLIP RR	\$ na 20.00 X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$ na 10.00 X
1SET BUMPER RETAINER CLIP LH RR	\$ na 20.00 X
1 BUMPER CLIP FRT	\$ na 85.00 6652
1 BUMPER GRILLE LOWER CLIP	\$ na 70.00 X
1 FENDER CLIP	\$ na 65.00 X
1 FENDER LINER CLIP	\$ na 60.00 —
TOTAL	\$ 373.00
TOTAL PARTS	\$ 3,672.30

LABOUR

Trans-cab Auto Services Pte Ltd

AAD2103-115

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD106M

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	4001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	~ 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	4 170.00	X
To repair and realign rear exhaust pipe.	\$	4 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	4 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	4 170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	601
To Check Electrical Lighting Concerned.	\$	170.00	201

TOTAL \$ 7,580.00**Over All Total \$ 14,551.60****(LUMP SUM)**

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: