

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD106M**AAD2103-115***Not Authorised
1/Smg @ 2600/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

23 MAR 2021**SHD106M**

VF1ABL15AUC282174

RENAULT

LATITUDE

22/03/2021

III

14/08/2015

PART**LIST**

- 1 BUMPER COVER FRT
- 1 BUMPER ABSORBER FRT
- 1 BUMPER BEAM FRT
- 1 BUMPER BRACKET KIT FRT RH
- 1 FENDER PANEL FRT RH
- 1 WHEELARCH FRT RH
- 1 HEADLAMP RH
- 1 BUMPER FOG LAMP GRILLE RH
- 1 WIPER RESERVOIR

\$	Bu	747.20	✓
\$	Sm	394.68	X
\$	R	663.70	X
\$	Div	101.40	✓
\$	Ry	437.10	✓
\$	cm	191.40	✓
\$	mgcm	743.60	✓
\$	DII	207.21	✓
\$	rn	179.60	X

\$ 3,665.89**10% \$ 366.59****\$ 3,299.30****Special Nett**

- 1SET BUMPER BRACKET CTR CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET BUMPER BRACKET SIDE CLIP LH RR
- 1SET BUMPER RETAINER CLIP LH RR
- 1 BUMPER CLIP FRT
- 1 BUMPER GRILLE LOWER CLIP
- 1 FENDER CLIP
- 1 FENDER LINER CLIP

\$	na na	33.00	X
\$	na	10.00	X
\$	na	20.00	X
\$	na	10.00	X
\$	na	20.00	X
\$	na	85.00	6652
\$	na	70.00	X
\$	na	65.00	X
\$	na	60.00	✓

TOTAL \$ 373.00**TOTAL PARTS \$ 3,672.30****LABOUR**

Trans-cab Auto Services Pte Ltd**AAD2103-115**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD106M

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	4001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	~ 170.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	4 170.00 X
To repair and realign rear exhaust pipe.	\$	170.00	4 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	4 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	4 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	4 170.00 X
To check steering geometry and computer wheel alignment	\$	220.00	601
To Check Electrical Lighting Concerned.	\$	170.00	201

TOTAL \$ 7,580.00**Over All Total \$ 14,551.60****(LUMP SUM)**

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

AAD2103-115

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD106M

Repair Days

10 DAYS