

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

KOA HEAN KIONG
 36 FERVALE LINK #19-19
 SINGAPORE 797533

Contact : 98225594

TP AXA
 Jasper.

ESTIMATE

Repair Code : CLM15209

Date in : 23/03/2021

Vehicle Num. : SMK6417E

Model : NISSAN SYLPHY 1.6 CVT

Chassis/Eng# : MNTBBAB17Z0034931/HR16940729C

Parts and Labour Assesment

Description of part	Qty	Unit Price	946. Amount
FRONT BONNET <i>Dented</i>	1	1061.30	1,061.30
FRONT BONNET LOCK <i>Dented</i>	1	51.40	51.40
FRONT BONNET RUBBER SEAL <i>new</i>	1	28.00	28.00
FRONT BONNET RUBBER STOPPER L/R <i>new</i>	2	12.00	24.00
FRONT BONNET SPONGE CLIPS <i>new</i>	8	3.00	24.00
FRONT BUMPER <i>Dented</i>	1	654.70	654.70
FRONT BUMPER LH FOGLAMP GARNISH <i>Cracked</i>	1	124.80	124.80
FRONT BUMPER LOWER GRILLE <i>Cracked</i>	1	290.50	290.50
FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	572.20	572.20
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	24.10	48.20
FRONT BUMPER SPONGE <i>Cracked</i>	1	234.90	234.90
FRONT BUMPER TOW HOOK COVER <i>new. Dented</i>	1	39.80	39.80
FRONT GRILLE <i>Cracked</i>	1	495.50	495.50
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	64.90	64.90
FRONT GRILLE TOP GARNISH <i>Dented</i>	1	404.80	404.80
FRONT HEADLAMP L/R <i>Cracked</i>	2	953.00	1,906.00
FRONT HEADLAMP LOWER BRACKET L/R <i>new</i>	2	29.00	58.00
REAR BOOTLID <i>Dented</i>	1	1199.90	1,199.90

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

KOA HEAN KIONG
 36 FERNVALE LINK #19-19
 SINGAPORE 797533

Contact : 98225594

ESTIMATE

Repair Code : CLM15209

Date in : 23/03/2021

Vehicle Num. : SMK6417E

Model : NISSAN SYLPHY 1.6 CVT

Chassis/Eng# : MNTBBAB17Z0034931/HR16940729C

REAR BOOTLID 'LOGO' EMBLEM	1	50.00	✓	50.00
REAR BOOTLID 'SYLPHY' EMBLEM	1	94.40	✓	94.40
REAR BOOTLID HINGES L/R	2	61.30	+	122.60
REAR BOOTLID INNER RUBBER GUIDE STOPPER L/R	2	15.00	+	30.00
REAR BOOTLID INNER TRIM BOARD	1	143.30	+	143.30
REAR BOOTLID LH REFLECTOR	1	130.00	+	130.00
REAR BOOTLID LOCK STRIKER	1	63.70	+	63.70
REAR BOOTLID MECHANISM LOCK	1	70.90	✓	70.90
REAR BOOTLID OUTER CHROME HANDLE	1	191.40	+	191.40
REAR BOOTLID WEATHER STRIP	1	90.80	✓	90.80
REAR BUMPER	1	752.90	632	752.90
REAR BUMPER LH REFLECTOR	1	61.90	✓	61.90
REAR BUMPER SIDE RETAINER L/R	2	38.20	382	76.40
REAR BUMPER SPONGE	1	78.00	✓	78.00
REAR END PANEL	1	454.30	✓	454.30
REAR END PANEL INNER TOP GARNISH	1	102.10	✓	102.10
REAR EXHAUST GASKET	1	15.00	✓	15.00
REAR EXHAUST HEAT COVER	1	103.40	+	103.40

*** This is a computer-generated document which requires no signature.***

page 2

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

KOA HEAN KIONG

36 FERNSVALE LINK #19-19

SINGAPORE 797533

Contact : 98225594

ESTIMATE

Repair Code : CLM15209

Date in : 23/03/2021

Vehicle Num. : SMK6417E

Model : NISSAN SYLPHY 1.6 CVT

Chassis/Eng# : MNTBBAB17Z0034931/HR16940729C

REAR EXHAUST RUBBER MOUNTING	<i>new</i>	3	35.40	<i>287</i>	106.20
REAR FENDER INNER TRIM L/R	<i>LH torn</i>	2	430.70	<i>430.70</i>	861.40
REAR FLOOR PANEL	<i>Buckled</i>	1	788.70	✓	788.70
REAR FLOOR PANEL SPONGE TRAY	<i>cancel</i>	1	177.40	✓	177.40
REAR FLOOR PANEL TOP BOARD COVER	<i>dent</i>	1	433.70	<i>356</i>	433.70
REAR LH END PANEL NOSE BRACKET	<i>dent</i>	1	96.90	✓	96.90
REAR LH FENDER	<i>Rep</i>	1	1471.30	✓	1,471.30
REAR LH FENDER INNER SHIELD	<i>torn</i>	1	38.00	✓	38.00
REAR LH TAILLAMP PANEL	<i>dent</i>	1	250.20	✓	250.20
REAR TAILLAMP L/R	<i>LH cancel</i>	2	344.30	<i>344.30</i>	688.60
Subtotal before discount					14,826.40
Percentage discount 10%					1,482.64
Sub-total 1					13,343.76
FRONT BONNET AIR CONDITION STICKER	<i>new</i>	1	80.00	<i>20</i>	80.00
FRONT BONNET CAUTION STICKER	<i>new</i>	1	80.00	<i>20</i>	80.00
FRONT BUMPER CLIPS - SET	<i>new</i>	1	50.00	<i>30</i>	50.00
FRONT BUMPER LH FOGLAMP	<i>cancel</i>	1	321.60	✓	321.60
FRONT BUMPER NUMBER PLATE	<i>Missing</i>	1	25.00	✓	25.00

*** This is a computer-generated document which requires no signature.***

page 3

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

KOA HEAN KIONG

36 FERNVALE LINK #19-19

SINGAPORE 797533

Contact : 98225594

ESTIMATE

Repair Code : CLM15209

Date in : 23/03/2021

Vehicle Num. : SMK6417E

Model : NISSAN SYLPHY 1.6 CVT

Chassis/Eng# : MNTBBAB17Z0034931/HR16940729C

FRONT BUMPER NUMBER PLATE HOLDER	2020	1	50.00	300	50.00
FRONT GRILLE CLIPS - SET	Xlu	1	40.00	20	40.00
REAR BOOTLID INNER TRIM BOARD CLIPS - SET	Nlu m	1	50.00	+	50.00
REAR BOOTLID NUMBER PLATE	Xlu n	1	25.00	+	25.00
REAR BOOTLID OUTER CHROME HANDLE CLIPS - SET	Xlu n	1	40.00	+	40.00
REAR BUMPER CLIPS - SET	Xlu	1	50.00	30	50.00
REAR BUMPER REVERSE SENSOR	2020	1	250.00	20	250.00
REAR END PANEL ANTENNA SENSOR	re n	1	66.70	+	66.70
REAR END PANEL INNER TOP GARNISH CLIPS - SET	Xlu	1	40.00	20	40.00
REAR EXHAUST SILENCER BOX	Bent	1	1120.90	884	1,120.90
REAR FENDER INNER TRIM CLIPS L/R - SET	Xlu	2	30.00	30	60.00
REAR FLOOR PANEL INSULATOR MAT	Nlu	1	200.00	-	200.00
REAR LH FENDER GLASS SEALANT	Xlu m	1	60.00	+	60.00
REAR LH FENDER GLASS WITH MOULDING	re n	1	532.00	+	532.00
REAR LH FENDER INNER SHIELD CLIPS - SET	Xlu	1	20.00	10	20.00
REAR TAILLAMP CLIPS L/R - SET	Nlu	2	30.00	10	60.00
REAR WINDSCREEN SEAL	{ Nlu re n	1	100.00	+	100.00
REAR WINDSCREEN SEALANT		1	80.00	+	80.00

*** This is a computer-generated document which requires no signature.***

page 4

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

KOA HEAN KIONG
36 FERNVALE LINK #19-19
SINGAPORE 797533

Contact : 98225594

ESTIMATE

Repair Code : CLM15209

Date in : 23/03/2021

Vehicle Num. : SMK6417E

Model : NISSAN SYLPHY 1.6 CVT

Chassis/Eng# : MNTBBAB17Z0034931/HR16940729C

Subtotal before discount	3,401.20
Percentage discount 0%	1850.60 0.00
Sub-total 2	3,401.20
Parts-total	16,744.96

LABOUR

To Transfer Rear Bootlid Mechanism Lock Outer Handle Reflector	60 80.00
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	✓ 80.00
To remove, reinstall fender glass	+ 100.00
To remove and refit rear windscreen(to FR)	+ 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80 140.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	3700 1100 1,600.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	600 1,000.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	80 120.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1600 1,800.00
To apply anti-rust chemical on repaired and replaced panel.	✓ 100.00
Labour Total	5,170.00
Parts & Labour Total	21,914.96

LKK Auto Consultants hence notify the Repairer of the following.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*** This is a computer-generated document which requires no signature.***

page 5

Adrian L
L/S 24/03/21

13 Days
Total: 15412.26
L/S: 12.3K ✓