

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLM2933J
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2190310/YISHUN
 Date: 05 Apr 2021
 Policy No: 5088703089-03
 Veh Reg No: SLM2933J
 Make/Model: TOYOTA TOYOTA
 COROLLA AXIO 1.5G
 MT

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 20/03/2021
 TP Veh Reg No: SKX513E

Not Authorised

Recovery B4 paint

4 days

Chassis No: NZE1617122157
 Engine No: 1NZE939345
 Reg. Date: 27/03/2017

Estimate Repair Cost to Vehicle No :SLM2933J

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	530.50	1 PC	530.50	✓
2 REAR BUMPER RH SIDE RETAINER	96.30	1 PC	96.30	✓
3 REAR BUMPER RH REFLECTOR	60.30	1 PC	60.30	X
4 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
5 RH TAILLAMP	560.98	1 PC	560.98	✓
6 RH TAILLAMP LOWER RETAINER	59.80	1 PC	59.80	X
			1,328.88	
	Less 25%		332.22	996.66
Labour				
7 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, KNOCK & REPAIR REAR RH FENDER, REAR PANEL & REALIGN THE SAME	600.00	1 LA	600.00	450
8 PUTTY & RESPRAY ON REAR RH FENDER, REAR PANEL, REAR BUMPER	700.00	1 LA	700.00	560
9 REMOVE & REFIX REVERSE SENSOR	40.00	1 LA	40.00	✓
			1,340.00	1,340.00
			Total	S\$ 2,336.66
			Add GST @ 7%	163.57
			Total Amount Payable	S\$ 2,500.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE