



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2104110
INV Date 11/06/2021
Reference CC4/LPC21003769/Epa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SGC 9339R
Insured Veh. GBD 5811Z
Claim No. 21/21/21/VC00/024328
Policy No. Z/21/VC00/109677
Accident Date 14/03/2021
Inspection Date 06/04/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC21003769/Epa3q2

Date: 11/06/2021

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 5811Z	Veh. Inspected	SGC 9339R
Policy No.	Z/21/VC00/109677	Coverage (\$)	0.00
Claim No.	21/21/21/VC00/024328	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	24/03/2021

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E200	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD2120342B095192	Colour	GREY
Odometer	63459 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R18	GENERAL	5 mm
L/H Front Tyre	245/40 R18	GENERAL	5 mm
R/H Rear Tyre	245/40 R18	GENERAL	5 mm
L/H Rear Tyre	245/40 R18	GENERAL	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/03/2021	Inspection Date	06/04/2021
Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGC 9339R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	DENTED	1,668.90	1,668.90
1	REAR BOTTOM BLACK TRIM BUMPER (SN)	CUT	247.17	247.17
1	REAR BUMPER CHROME MOULDING (SN)	CUT	169.95	169.95
1	LH/REAR BUMPER CHROME MOULDING (SN)	NECESSARY	137.18	137.18
1	RH/REAR BUMPER CHROME MOULDING (SN)	NECESSARY	137.18	137.18
1	LEFT BOTTOM BRACKET (SN)	NECESSARY	24.88	24.88
1	RIGHT BOTTOM BRACKET (SN)	NECESSARY	24.88	24.88
1	CTR/ BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	267.18	-
3	GROMMET (SN)	NECESSARY	7.92	7.92
1	MERCEDES STAR (SN)	NECESSARY	49.73	49.73
1	E200 MODEL PLATE (SN)	NECESSARY	91.89	91.89
1	OUTER RIGHT REAR LAMP COMBINATION (SN)	NOT NECESSARY	704.32	-
			3,531.18	2,559.68
LABOUR				
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.			1,920.00	960.00
RESPRAY REAR BUMPER & TRUNK LID .			1,500.00	1,200.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.			380.00	380.00
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE .			120.00	120.00
			3,920.00	2,660.00
GRAND TOTAL			7,451.18	5,219.68
RECOMMENDED COST OF REPAIRS				5,219.68

Report Ref No. CC4/LPC21003769/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGC 9339R

INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGC 9339R

RE-INSPECTION

