



Mercedes-Benz

Steve (LKK)
6/4/21, 19.30ca

wz PL
PIP
My BAL SLJ
4 dys

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGC9339R

LONPAC INSURANCE BHD
MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information
WIP No 48961
Reg No/Reg Date SGC9339R / 23/12/2014
Date In/Mileage
Chassis No WDD2120342B095192
Engine No 27492030307485
Make/Model MB/E 200 2.0 CGI SEDAN (W212)
Colour/Trim 027 755 Tenorite Gr/ 042 258 Basalt Grey

Account No	Terms	Date/Time Printed	CSE	Operator
WL001605	Credit	15/03/2021/ 18:19	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
THIS IS NOT AN OFFICIAL TAX INVOICE				
ESTIMATE				
Z REQUEST Customer Request M BPN50N POLICY NO/ACC DATE : GA148647/1 // 14-3-2021 DRIVE IN/TP VEH NUMBER : 15-3-2021 // GBD5811Z - LONPAC DATE IN/DATE SURVEY: DIRECT SETTLEMENT BY:				
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				960 1920.00
A BPIRES RESPRAY REAR BUMPER & TRUNK LID				1200 1500.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00 ✓
A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				120.00 ✓
M REAR BUMPER	1.00	1668.90	00.00	1668.90
M REAR BOTTOM BLACK TRIM BUMPER	1.00	247.17	00.00	247.17
M REAR BUMPER CHROME MOULDING	1.00	169.95	00.00	169.95
M LH/REAR BUMPER CHROME MOULDING	1.00	137.18	00.00	137.18
M RH/REAR BUMPER CHROME MOULDING	1.00	137.18	00.00	137.18
M LEFT BOTTOM BRACKET	1.00	24.88	00.00	24.88
M RIGHT BOTTOM BRACKET	1.00	24.88	00.00	24.88
M CTR/BASIC MOUNTING FOR BUMPER	1.00	267.18	00.00	267.18
M GROMMET	3.00	2.64	00.00	7.92
M MERCEDES STAR	1.00	49.73	00.00	49.73
M E200 MODEL PLATE	1.00	91.89	00.00	91.89
M OUTER RIGHT REAR LAMP COMBINATION	1.00	704.32	00.00	704.32

Confirmed & accepted by

Go Chee Han

DID : 6771 4336 HP : 9181 7717

Email : cheehan.go@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Nett 7,451.18

7% GST on 7451.18 521.58

Total Payable 7,972.76

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Supplementary terms must be reviewed and is subject to final approval from insurance company

Acknowledged by Repairer



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg