

SmartOne Auto Pte. Ltd.

Co. Reg No: 201939368E

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: smartoneauto@gmail.com



DATE : 12.04.21

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS
VEHICLE NO : **EU8810G**
MODEL : **HONDA FIT**
DATE OF ACCIDENT : 21.03.21
TIME OF ACCIDENT : 22:15HRS

Vecon.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Dented</i>	1	\$ 849.90	\$ 849.90
2	TAIL GATE WINDSCREEN MOULDING <i>new</i>	2	\$ 76.00	\$ 152.00
3	TAIL GATE INNER LOCK <i>Damaged</i>	1	\$ 169.40	\$ 169.40
4	TAIL GATE LOCK CATCH <i>new</i>	1	\$ 25.00	\$ 25.00
5	TAIL GATE WEATHER STRIP <i>lit</i>	1	\$ 134.50	\$ 134.50
6	TAIL GATE INNER TRIM <i>cracked</i>	1	\$ 372.20	\$ 372.20
7	REAR BUMPER <i>Dented</i>	1	\$ 490.00	\$ 490.00
8	REAR BUMPER TOW HOOK COVER <i>new</i>	1	\$ 24.20	\$ 24.20
9	REAR BUMPER BRACKET <i>new</i>	2	\$ 54.10	\$ 108.20
10	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 35.20	\$ 70.40
11	TAIL LAMP <i>new</i>	2	\$ 296.10	\$ 592.20
12	TAIL LAMP LOWER BRACKET <i>new</i>	2	\$ 17.20	\$ 34.40
13	REAR FENDER INNER COWLING <i>3 new</i>	2	\$ 78.10	\$ 156.20
14	REAR FENDER INNER TRIM	2	\$ 298.90	\$ 597.80
15	REAR END PANEL <i>Dented</i>	1	\$ 356.70	\$ 356.70
16	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 116.20	\$ 116.20
17	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$ 185.60	\$ 185.60
18	REAR TOOLS COMPARTMENT <i>cracked</i>	1	\$ 294.20	\$ 294.20

3103.90

2483.12

TOTAL PRICE \$ 4,729.10
LESS 20% \$ 945.82
SUB TOTAL PRICE \$ 3,783.28

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE (SPECIAL TYPE) <i>new</i>	1	\$ 180.00	\$ 180.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	TAIL GATE OUTER MOULDING CLIP (SET) <i>2 new</i>	1	\$ 30.00	\$ 30.00
4	TAIL GATE INNER TRIM CLIP (SET) <i>1 new</i>	1	\$ 50.00	\$ 50.00
5	TAIL GATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : EU8810G
 MODEL : HONDA FIT
 DATE OF ACCIDENT : 21.03.21
 TIME OF ACCIDENT : 22:15HRS

6	TAIL GATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	✓
7	TAIL GATE EMBLEM " FIT" (SPECIAL TYPE) <i>new</i>	1	\$ 150.00	\$ 150.00	60
8	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
9	REAR FENDER INNER COWLING (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
10	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
11	REAR FENDER INNER UPPER TRIM (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
12	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
13	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	10
14	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	+
15	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	200
			TOTAL	\$ 1,660.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
8	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 80.00	50
9	REAR CHASSIS ALIGNMENT	\$ 250.00	x
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
11	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
12	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL

\$4,030.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : EU8810G
MODEL : HONDA FIT
DATE OF ACCIDENT : 21.03.21
TIME OF ACCIDENT : 22:15HRS

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,443.28
TOTAL LABOUR COST : \$ 4,030.00
TOTAL REPAIR COST : \$ 9,473.28

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR

MICHELLE

HP : 9856 4815

Adrian Lj

L/S 12/04/21.

06 Days. ✓

Total: 5063.12

L/S: AK.. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: