



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		Ms Quah Ai Chin 774 Yishun Avenue 3 #07-189 Singapore 760774 Mobile: 91827353		
			Document No. 39011704				
			Document Date 04/05/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	25/01/2021	SLK3909J	1261	20825	67/TP/SLK3909J
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKBBAB340L002963		M15AY099763	60	Sam San Joi	22/03/2021 10.36		04/05/2021 8.41
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI SUNDRIES TP CLAIM TP-GBH1772H ACC DATE:20/03/2021 DRIVE IN:22/03/2021 DATE-IN:30/03/2021 DATE SURVEY:30/03/2021 NO OF REPAIR DAYS:5 DAYS BY:TAUFIKH(LKK)				30.00	
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR ACCIDENT AREAS	0619			183.18	
3	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM	0741			350.00	
4	S	BP-SUBLET DRILL HOLE & INSTALL REAR REVERSE SENSOR	0742			180.00	
5	S	BP-SUBLET CHECK LIGHTING & OCNDUCT WATER LEAK TEST	0742			180.00	
6	S	BP-SUBLET TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE	0742			360.00	
7	S	BP-SUBLET REMOVE & INSTALL REAR REVERSE CAMERA	0742			180.00	
8	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			180.00	
9	S	BP-SUBLET REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	0742			1440.00	
10	S	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS	0742			1180.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details				Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept				S1000003 / ICCI1		Ms Quah Ai Chin 774 Yishun Avenue 3 #07-189 Singapore 760774 Mobile: 91827353			
				Document No. 39011704					
				Document Date 04/05/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2020	MXPJ10R	BHXNBQ A1	25/01/2021	SLK3909J	1261	20825	67/TP/SLK3909J		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDKBAB340L002963		M15AY099763	60	Sam San Joi	22/03/2021	10.36	04/05/2021	8.41	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
11	1	T52453-52902 GUARD, RR BUMPER,				1.00	500.50		500.50
12	2	T52563-52060 RETAINER, RR BUMPER,				1.00	59.80		59.80
13	3	T52562-52100 RETAINER, RR BUMPER,				1.00	59.80		59.80
14	4	T67005-52E00 PANEL SUB-ASSY, BACK				1.00	1424.10		1424.10
15	5	T68105-52770 GLASS SUB-ASSY, BACK				1.00	1187.70		1187.70
16	6	T75403-75010 EMBLEM SUB-ASSY,				1.00	62.20		62.20
17	7	T75442-52550 PLATE, BACK DOOR				1.00	40.90		40.90
18	8	T75442-52560 PLATE, LUGGAGE COMPT				1.00	40.90		40.90
19	9	T75441-52270 PLATE, LUGGAGE COMPT				1.00	45.60		45.60
20	0	T89348-K0230 RETAINER, ULTRASONIC				1.00	15.20		15.20
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 7,699.88		
			Please acknowledge receipt of vehicle		Parts	3,436.70	GST 7.00%		538.99
					Labour	30.00	Less		0.00
					Sublet	4,233.18			
					Lubrication/Fluid	0.00			
					Others	0.00	Amount Due		8,238.87

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		Ms Quah Ai Chin 774 Yishun Avenue 3 #07-189 Singapore 760774 Mobile: 91827353		
			Document No. 39011704				
			Document Date 04/05/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXPJ10R	BHXNBQ A1	25/01/2021	SLK3909J	1261	20825	67/TP/SLK3909J
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKBBAB340L002963		M15AY099763	60	Sam San Joi	22/03/2021 10.36		04/05/2021 8.41
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI SUNDRIES TP CLAIM TP-GBH1772H ACC DATE:20/03/2021 DRIVE IN:22/03/2021 DATE-IN:30/03/2021 DATE SURVEY:30/03/2021 NO OF REPAIR DAYS:5 DAYS BY:TAUFIKH(LKK)				30.00	
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR ACCIDENT AREAS	0619			183.18	
3	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM	0741			350.00	
4	S	BP-SUBLET DRILL HOLE & INSTALL REAR REVERSE SENSOR	0742			180.00	
5	S	BP-SUBLET CHECK LIGHTING & OCNDUCT WATER LEAK TEST	0742			180.00	
6	S	BP-SUBLET TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE	0742			360.00	
7	S	BP-SUBLET REMOVE & INSTALL REAR REVERSE CAMERA	0742			180.00	
8	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			180.00	
9	S	BP-SUBLET REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	0742			1440.00	
10	S	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS	0742			1180.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details				Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept				S1000003 / ICCI1		Ms Quah Ai Chin 774 Yishun Avenue 3 #07-189 Singapore 760774			
				Document No. 39011704					
				Document Date 04/05/2021		Mobile: 91827353			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2020	MXPJ10R	BHXNBQ A1	25/01/2021	SLK3909J	1261	20825	67/TP/SLK3909J		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDKBAB340L002963		M15AY099763	60	Sam San Joi	22/03/2021	10.36	04/05/2021	8.41	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
11	1	T52453-52902 GUARD, RR BUMPER,				1.00	500.50		500.50
12	2	T52563-52060 RETAINER, RR BUMPER,				1.00	59.80		59.80
13	3	T52562-52100 RETAINER, RR BUMPER,				1.00	59.80		59.80
14	4	T67005-52E00 PANEL SUB-ASSY, BACK				1.00	1424.10		1424.10
15	5	T68105-52770 GLASS SUB-ASSY, BACK				1.00	1187.70		1187.70
16	6	T75403-75010 EMBLEM SUB-ASSY,				1.00	62.20		62.20
17	7	T75442-52550 PLATE, BACK DOOR				1.00	40.90		40.90
18	8	T75442-52560 PLATE, LUGGAGE COMPT				1.00	40.90		40.90
19	9	T75441-52270 PLATE, LUGGAGE COMPT				1.00	45.60		45.60
20	0	T89348-K0230 RETAINER, ULTRASONIC				1.00	15.20		15.20
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary			Total 7,699.88		
		Please acknowledge receipt of vehicle		Parts	3,436.70	GST 7.00% 538.99			
				Labour	30.00	Less 0.00			
				Sublet	4,233.18				
				Lubrication/Fluid	0.00				
				Others	0.00	Amount Due 8,238.87			

Company Copy