



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

IMMEDIATE ADVICE

To : AXA Insurance Pte Ltd

DATE: 26/3/21

Survey details

Date of loss	19/3/2021
Date of appointment	24/3/2021
Date of survey	25/3/2021
Location of survey	KING'S AUTO AIR-CONDITIONING SERVICE

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	SMJ 3991M
Make and Model	HONDA INSIGHT 1.3G A
Date of registration	1/7/2009
Excess	
Market Value	\$24,000.00
Part Rebate	\$9,739.00
Nett Loss	\$14,261.00

Repair details

Initial Estimate	
------------------	--

Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	
Number of days of repair	5 days (est)

Remarks:

The estimated repair cost of the damaged vehicle is in the region of \$3,000.00-\$4,000.00