



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept				S1000003 / ICCI1		Mr Alvin Chung Wing Kit (Alvin Zeng Yongjie) 767 Woodlands Circle #07-340 Singapore 730767 Mobile: 98554426			
				Document No. 0					
				Document Date 24/03/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	ZGE20R	HPXNP S6	21/11/2017	SLU0242R	0	20828	67/TP/SLU0242R		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDGG20W90J008263		2ZR0A30979	60	Sam San Joi	23/03/2021 17.00		--/--/---- 0.00		
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount			
1	Z	BP-SUNDRIY-AI SUNDRIES TP CLAIM TP-GBJ2010G ACC DATE:23/03/2021 DRIVE IN:23/03/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				✓ 30.00			
2	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				✓ 180.00			
3	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				✓ 180.00			
4	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR				✓ 360.00			
5	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS				✓ 462.00			
6	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM				✓ 350.00			
7	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA				✓ 180.00			
8	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE				✓ 360.00			
9	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				✓ 180.00			
10	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				✓ 3600.00			
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total		
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
							Amount Due		

Customer Copy



Borneo Motors

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Alvin Chung Wing Kit (Alvin Zeng Yongjie) 767 Woodlands Circle #07-340 Singapore 730767 Mobile: 98554426
	Document No. 0	
	Document Date 24/03/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	21/11/2017	SLU0242R	0	20828	67/TP/SLU0242R
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDGG20W90J008263	2ZR0A30979	60	Sam San Joi	23/03/2021	17.00	--/--/---	0.00


L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS			2360	2950.00
12	1	T52159-68907 REAR BUMPER COVER,	1.00	591.80		591.80
13	2	T52576-68020 L/R SIDE BPR RETAINER,	1.00	46.00		46.00
14	3	T52156-68030 L/RR BUMPER SUPPORT,	1.00	97.40		97.40
15	4	T52575-68020 R/R SIDE BPR RETAINER	1.00	46.00		46.00
16	5	T52155-68030 R/RR BUMPER SUPPORT	1.00	97.40		97.40
17	6	S52161-0K040 CLIPS	10.00	4.10		41.00
18	7	T58307-68031 REAR LOWER FLR PANEL,	1.00	536.70		536.70
19	8	T52181-68010 ARM,RR BUMPER	2.00	53.80		107.60
20	9	T57655-68010 REAR FLOOR MEMBER 2,	1.00	110.50		110.50
21	0	T57666-68010 L/R LWR BACK PANEL,	1.00	58.80		58.80
22	1	T58035-68010 R/RR FLOOR EXTENSION,	1.00	93.90		93.90
23	2	T67935-68020 B0 PLATE BACK DOOR	1.00	298.00		298.00
24	3	T67005-68041 PANEL ASSY, BACK DOOR	1.00	1477.30		1477.30
25	4	T67881-68030 WEATHERSTRIP, BACK	1.00	335.70		335.70
26	5	T68105-68071 REAR BACK DOOR GLASS,	1.00	1065.90		1065.90
27	6	T67750-68020 B1 REAR BACK DOOR BOARD,	1.00	363.70		363.70
28	7	T69350-28151 LOCK ASSY, BACK DOOR	1.00	412.70		412.70
29	8	T69430-28050 STRIKER ASSY, BACK	1.00	40.90		40.90

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors



TOYOTA

ichcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		Mr Alvin Chung Wing Kit (Alvin Zeng Yongjie) 767 Woodlands Circle #07-340 Singapore 730767 Mobile: 98554426			
			Document No. 0					
			Document Date 24/03/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZGE20R	HPXNP S6	21/11/2017	SLU0242R	0	20828	67/TP/SLU0242R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDGG20W90J008263		2ZR0A30979	60	Sam San Joi	23/03/2021 17.00		--/--/--- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
30	9	T90975-02086 FRONT BONNET EMBLEM,			1.00	72.20		rel / 72.20
31	0	T75444-68010 PLATE, LUGGAGE COMPT (VALVE MAT)			1.00	41.10		rel / 41.10
32	1	T75443-ELGAN ELEGANCE EMBLEM			1.00	40.00		rel / 40.00
33	2	T76811-68130 GARNISH, BACK DOOR,			1.00	290.30		chr / 290.30
34	3	T76817-50010 CLIP, BACK DOOR			4.00	2.40		rel / 9.60
35	4	T75819-33010 CLIP, LUGGAGE			2.00	3.90		rel / 7.80
36	5	T81591-68020 LENS & BODY, RR			1.00	294.10		rel / 294.10
37	6	T81581-68020 LENS & BODY, RR			1.00	294.10		chr / 294.10
38	7	T81271-72011 LENS, LICENSE LAMP			2.00	31.00		rel / 62.00
39	8	T89997-30070 ELECTRICAL ANTENNA,			1.00	192.20		rel / 192.20
40	9	SPZ061-12010 24 1G3 SENSOR			1.00	151.60		rel / 151.60
41	0	T04562-12010 FRT W/SCREEN DAM KIT,			1.00	121.00		rel / 121.00
42	1	T21000-20 SIKI 182010 SIKI TACK GO! (BLA			2.00	108.00		rel / 216.00
43	2	T21000-22 SIKI 207. G+P ADHESIVE PRIMER			1.00	200.00		rel / 200.00
<i>Taufik 97495747 / 67563561</i> <i>WP 25/3/21 @ 145pm</i> <i>*Resurvey before paint</i> <i>8 days.</i> <i>taufik@thdauto.com</i>								
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 16,645.30	
LKK Auto Consultants hereby notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			I hereby acknowledge receipt of vehicle		Parts 7,813.30		GST 7.00% 1,165.17	
					Labour 8,482.00		Less 0.00	
					Sublet 350.00			
					Lubrication/Fluid 0.00			
					Others 0.00		Amount Due 17,810.47	

Acknowledged by Repairer

Signature:

Date:

Customer Copy