

ASSIGNMENT

Veh No:

SJM 2951E Yr Rem 17

Page 2 of 3

Merimen e-Claims

SJM 2951E
TP/CHINA

EPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Mar 2021)
Parts: 143 HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJM2951E)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Other Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	*1	PC REAR BUMPER	0.00	0.00	*210.00 F
1	*1	PC REAR BUMPER REINFORCEMENT	0.00	0.00	*130.00 F
	*1	PC REAR BUMPER SPONGE	0.00	0.00	*65.00 F
	*3	PCS REAR BUMPER RETAINER BEAMS @15/PC	0.00	0.00	*45.00 F
	*6	PCS REAR BUMPER CLIPS @2/PC	0.00	0.00	*12.00 F
	*2	PCS TAILLAMPS @125/PC	0.00	0.00	*250.00 F
	*1	PC REAR BOOT	0.00	0.00	*350.00 F
	*1	PC REAR BOOT LOGO	0.00	0.00	*12.00 F
	*1	PC REAR BOOT EMBLEM (AVANTE)	0.00	0.00	*20.00 F
	*1	PC REAR BOOT INNER LOCK	0.00	0.00	*70.00 F
	*1	PC REAR BOOT INNER RUBBER	0.00	0.00	*42.00 F
	*1	PC REAR BOOT INNER SPONGE	0.00	0.00	*120.00 F
	*1	PC REAR CENTRE PANEL	0.00	0.00	*150.00 F
	*1	PC REAR CENTRE PANEL INNER TOP GARNISH	0.00	0.00	*25.00 F
	*2	PCS REAR BOOT REFLECTORS @85/PC	0.00	0.00	*170.00 F
	*2	PCS REAR BOOT HINGES @50/PC	0.00	0.00	*100.00 F
	*1	PC REAR LH FENDER	0.00	0.00	*580.00 F
	*1	PC REAR LH FENDER INNER GARNISH	0.00	0.00	*105.00 F
	*1	PC REAR LH FENDER TRIANGLE GLASS MOULDING	0.00	0.00	*180.00 F
	*1	PC REAR RH FENDER INNER GARNISH	0.00	0.00	*105.00 F
	*1	PC REAR SPARE TYRE COMPARTMENT	0.00	0.00	*340.00 F
	*1	PC REAR SPARE TYRE TOP BOARD	0.00	0.00	*128.00 F
	*1	PC REAR WINDSCREEN GLASS MOULDING	0.00	0.00	*20.00 F

Total Parts (\$\$)

3,229.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Not Withheld
11/12/2020 @ 4300h
Resurvey After Paint
9 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary survey must be surveyed and is subject to final approval from Insurance Company

Acknowledged by

Signature:

Date:

REF: CT2/21003805/Kg

ASSIGNMENT

Veh No:

STM 2951E

Yr

17

Page 3 of 3

Merimen e-Claims

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

- | | | |
|---|---|--------------------------------|
| 1 | 1 | 1 PC REAR LH FENDER GLASS GUM |
| 2 | 1 | 1 PC REAR WINDSCREEN GLASS GUM |
| 3 | 1 | 1 SET REVERSE SENSOR |

30.00

40.00

200.00

Sub Total (S\$)

270.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

- | | | | | |
|---|--|-----|----------|------|
| 1 | REMOVE & REFIX REAR WINDSCREEN GLASS | New | 100.00 | ✓ |
| 2 | REMOVE & REFIX REAR LH FENDER GLASS | New | 60.00 | 50 |
| 3 | PANEL BEATING | New | 1,300.00 | 1200 |
| 4 | REMOVE & REFIX SEAT, CARPET, GARNISH, TOP ROOF LINING, ETC | New | 100.00 | ✓ |
| 5 | PUTTY & RESPRAY ON REAR BOTH FENDERS, REAR BOOT, HINGES, REAR PANEL, REAR SPARE TYRE COMPARTMENT, BUMPER | New | 1,000.00 | 900 |
| 6 | RUSTPROOFING | New | 90.00 | ✓ |

Gross Labour Cost (S\$)

2,650.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >