

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S: TAY HOCK CHYE
158 MARIAM WAY #03-01
SINGAPORE 507083

ATTN:

Your Ref No: TP 0321-6292
Claim Type: Third Party
Accident Date: 13/03/2021
TP Veh Reg No: GBB 7744 G

TP Chien
Xiao Chen.

Estimate No: EST1506764
Date: 13 Mar 2021
Policy No: 2100392961-06
Veh Reg No: SKQ2855S
Make/Model: MAZDA MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF
Chassis No: JM6CW1071F0120431
Engine No: PE30715731
Reg. Date: 18/11/2014

Estimate Repair Cost to Vehicle No :SKQ2855S

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BUMPER <i>Repair</i>	962.0000	1 PC	962.00 ✓	
2 REAR BUMPER CLIPS	5.0000	10 PC	50.00 +	
3 REAR BUMPER SIDE HOLDER - LH	48.0000	1 PCS	48.00 +	
4 REAR BUMPER SIDE HOLDER - RH	48.0000	1 PCS	48.00 +	
5 REAR FENDER - RH	2,428.0000	1 PC	2,428.00 +	
6 REAR FENDER GLASS W/MOULDING - RH <i>new</i>	570.0000	1 PCS	570.00 ✓	
7 REAR BOOT <i>Dented</i>	1,637.0000	1 PCS	1,637.00 ✓	
8 REAR BOOT GLASS <i>Shattered</i>	1,126.0000	1 PCS	1,126.00 ✓	
9 REAR BOOT GLASS MOULDING <i>3m</i>	61.0000	1 SET	61.00 ✓	
10 REAR BOOT MAZDA LOGO <i>3601</i>	45.0000	1 PCS	45.00 ✓	
11 REAR BOOT RUBBER <i>new</i>	178.0000	1 PC	178.00 ✓	
12 REAR BOOT E WORDING <i>new</i>	82.0000	1 PCS	82.00 ✓	
13 REAR BOOT SKYACTIV TECHNOLOGY LOGO <i>new</i>	80.0000	1 PCS	80.00 ✓	
			7,315.00	
		Less 20%	1,463.00	5,852.00
Special Net				
14 REAR FENDER GLASS V COOL - RH <i>new</i>	150.0000	1 PCS	150.00 <i>120</i>	
15 REAR BOOT GLASS V-KOOL <i>new</i>	350.0000	1 PCS	350.00 <i>250</i>	
16 SEALANT <i>3m</i>	20.0000	3 PCS	60.00 ✓	
17 SPONGE TAPE <i>400</i>	20.0000	1 PC	20.00 ✓	
			580.00	580.00
Labour				
18 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	500.0000	1 JOB	500.00 <i>200</i>	
19 TO RESPRAY PAINT ON ACCIDENT PORTIONS	600.0000	1 JOB	600.00 <i>400</i>	
20 TO TUFF-KOTE	30.0000	1 JOB	30.00 ✓	
21 TO TRANSFER REAR BUMPER SENSOR	100.0000	1 JOB	100.00 <i>50</i>	
22 TO REMOVE, REFIT REAR GARNISH, CARPET & RELATED PARTS	150.0000	1 JOB	150.00 +	
23 TO REMOVE, REPLACE REAR FENDER GLASS - RH	60.0000	1 JOB	60.00 ✓	
24 TO REMOVE, REPLACE REAR BOOT GLASS	120.0000	1 JOB	120.00 ✓	
25 TO VACUUM GLASS	60.0000	1 JOB	60.00 ✓	
			1,620.00	1,620.00

920

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : TAY HOCK CHYE
158 MARIAM WAY #03-01
SINGAPORE 507083

ATTN:

Your Ref No: TP 0321-6292
Claim Type: Third Party
Accident Date: 13/03/2021
TP Veh Reg No: GBB 7744 G

Estimate No: **EST1506764**
Date: 13 Mar 2021
Policy No: 2100392961-06
Veh Reg No: **SKQ2855S**
Make/Model: MAZDA MAZDA5 5-
DOOR WAGON 2.0L
SP.6EAT SUNROOF
Chassis No: JM6CW1071F0120431
Engine No: PE30715731
Reg. Date: 18/11/2014

Estimate Repair Cost to Vehicle No :SKQ2855S

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 8,052.00
			Add GST @ 7%	563.64
			Total Amount Payable	SS 8,615.64

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND SIX HUNDRED FIFTEEN AND CENTS SIXTY FOUR ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj.
h/s 30/03/21
03 Days.
total: 4200.80
h/s: 3350.