

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : GBD 5282 A
Accident Date : 23-Mar-2021

No. : 31721

Accident Date : 23-Mar-2021

Date : 23-Mar-2021

Our Ref : 021090 (CHINA) / QUEK

PAGE : 1

MI YINLONG (MR)
Singapore

Not Authorized
PAGE : 87149.78

Runny After Point

6 days

ESTIMATED COST OF REPAIR FOR HONDA VE7EL 1 5Y CVT (2018) SLW4460R

QTY	DESCRIPTION	UNIT	PRICE	TOTAL	REMARKS
1	front bumper - top	pc			
1	front bumper - lower	pc			
1	front bumper lower centre grille	pc			
1	front bumper lower rubber	pc			
1	RH front bumper foglamp	pc			
1	RH front bumper foglamp cover	pc			
2	front bumper side retainer (LH/RH)	pcs			
1	front bumper reinforcement	pc			
2	front bumper reinforcement (LH/RH)	pcs			
2	top moulding	pc			
2	front bumper inner air guide	pc			
10	front bumper clips	pcs			
2	headlamp assy (LH/RH) o/smbcm	pcs			
2	headlamp lower bracket (LH/RH)	pcs			
1	front grille	pc			
2	front grille side bracket (LH/RH)	pcs			
1	front grille centre bracket	pc			
1	front grille outer garnish	pc			
1	front grille outer chrome	pc			
1	front grille logo	pc			
10	front grille clips	pcs			
1	front grille top garnish	pc			
8	front grille top garnish clips	pcs			
1	horn	pc			
1	wiper washer tank	pc			
1	wiper washer tank motor	pc			
1	RH front fender	pc			

JKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Renker

Dante:

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : GBD 5282 A
Our Ref : 021090

Page : 3
No. : 31721

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

750.00 *5501*

To focus headlamps. To check front
wiring and lighting operation.

50.00 *201*

To dismantle and check front under-
carriages. To replace affected
portions.

nn 240.00 *X*

To conduct front wheel alignment
test.

100.00 *601*

To putty and respray on affected
portions.

950.00 *8001*

Total :

S\$12,738.80
=====

Singapore Dollars Twelve Thousand Seven Hundred
and Thirty Eight and Cents Eighty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.