

ASS. REC. BY:

REF:

072/21003815/KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured: GBD 5282A

Policy No. DMCVSNW00113862003

Claims No. SNM21D201645/C02/TANKL

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLW4460R Yr Regn: 02, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c.

1496

Colour:

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading:

59868

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

R41

1232612

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

23/3/21

D.O.I.

25/3/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rn bulk

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/7/21

Kenneth confirmed \$7149.76 (Red 5589.04, 43%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

22/7/21-Typist

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format: Merimen

Lump Sum / I.B.I: (\$ 7149.76

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 31721

Date : 23-Mar-2021

Vehicle Insured : GBD 5282 A
Accident Date : 23-Mar-2021

Our Ref : 021090 (CHINA) / QUEK

PAGE : 1

MI YINLONG (MR)
Singapore

Not Authorized
6/8/21
Returning After Repair
6 days

ESTIMATED COST OF REPAIR FOR HONDA VEZEL 1.5X CVT (2018) SLW4460R

1 pc	front bumper - top		Ry 489.80	✓
1 pc	front bumper - lower		GM 195.60	✓
1 pc	front bumper lower centre grille		Dis 77.50	X
1 pc	front bumper lower rubber		Sm 89.90	X
1 pc	RH front bumper foglamp		my cm 327.00	✓
1 pc	RH front bumper foglamp cover		Sm 45.00	X
2 pcs	front bumper side retainer (LH/RH)	@ S\$ 17.50	discm 35.00	✓
1 pc	front bumper reinforcement		R 321.00	X
2 pcs	front bumper reinforcement top moulding (LH/RH)	@ S\$ 19.60	R 39.20	X
2 pcs	front bumper inner air guide	@ S\$ 36.00	Sm 72.00	X
10 pcs	front bumper clips	@ S\$ 3.50	Sm 35.00	✓
2 pcs	headlamp assy (LH/RH) o/s m/c m	@ \$1710.20	3,420.40	✓
2 pcs	headlamp lower bracket (LH/RH)	@ S\$ 35.00	M/c m 70.00	✓
1 pc	front grille		cm 351.80	✓
2 pcs	front grille side bracket (LH/RH)	@ S\$ 19.60	cm 39.20	✓
1 pc	front grille centre bracket		cm 38.70	X
1 pc	front grille outer garnish		GM 385.00	✓
1 pc	front grille outer chrome		75.00	✓
1 pc	front grille logo		Sm 23.40	✓
10 pcs	front grille clips	@ S\$ 3.50	Sm 35.00	✓
1 pc	front grille top garnish		dry 85.00	✓
8 pcs	front grille top garnish clips	@ S\$ 3.50	Sm 28.00	✓
1 pc	horn		Sm 58.50	X
1 pc	wiper washer tank		Sm 75.00	X
1 pc	wiper washer tank motor		Sm 58.60	X
1 pc	RH front fender		Ry 580.00	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : GBD 5282 A
Our Ref : 021090

Page : 2
No. : 31721

1 pc	RH front fender inner shield		Dis	130.00	✓
8 pcs	RH front fender inner shield clips	@ S\$ 3.50	nc	28.00	✓
2 pcs	front fender wheel arch garnish (LH/RH)	c/s/m/y @ S\$153.00	nc/m	306.00	✓
1 pc	bonnet		n	892.30	X
2 pcs	bonnet hinges (LH/RH)	@ S\$ 48.50	n	97.00	X
1 pc	bonnet lock		n	98.50	X
1 pc	bonnet pull lock cable		nc	42.50	X
1 pc	air con condenser		nc	868.10	✓
1 pc	front support panel			411.90	?
1 pc	RH front rim		nc	801.40	✓
1 pc	RH front shock absorber			430.10	?
1 pc	RH front shock absorber mounting			35.00	?
1 pc	RH front shock absorber stopper			26.90	?
1 pc	RH front shock absorber cover			32.00	?
1 pc	RH front knuckle arm			249.70	?
1 pc	RH front knuckle arm bearing			135.50	?
1 pc	RH front bearing hub			187.50	?
1 pc	RH front lower arm			380.00	?
1 pc	RH front stabilizer bar linkage		nc	60.00	X
1 pc	RH front tie rod			88.70	?
1 pc	RH front tie rod end			71.80	?

				12,423.50	
Less 20% :				-2,484.70	

				9,938.80	
1 pc	front number plate		nc	40.00	sn X
1 pc	RH front bumper foglamp wireharness (local repair)		nc	250.00	sn ✓
1 pc	RH front tyre		nc	420.00	sn X

Con't Page 3 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : GBD 5282 A
Our Ref : 021090

Page : 3
No. : 31721

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	750.00	5501
To focus headlamps. To check front wiring and lighting operation.	50.00	201
To dismantle and check front under- carriages. To replace affected portions.	240.00	7
To conduct front wheel alignment test.	100.00	601
To putty and respray on affected portions.	950.00	8001

Total :	S\$12,738.80	=====

Singapore Dollars Twelve Thousand Seven Hundred
and Thirty Eight and Cents Eighty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 23/03/2021 19:36 (SGT)
Date of Accident 23/03/2021 08:45 (SGT)
Exact Location of Accident Singapore
Additional Location Information JUNCTION OF LOYANG LANE AND LOYANG WAY
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLW4460R

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner MI YINLONG
NRIC No SXXXX347D
Email Address STEVENMI88@GMAIL.COM
Mobile Phone No (Phone) +65-96287685
Alternative Phone No (Home) +65-96287685

VEHICLE PARTICULARS

Manufacturer Honda
Model Vezel
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1496

INSURANCE COMPANY


Name of Insurance Company QBE Insurance (Singapore) Pte Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number V0027118-MVA
Cover Note Number -

DRIVER

Name of Driver MI YINLONG
NRIC No SXXXX347D

Describe Circumstances of the Accident

In the morning 8.25 Am I drive along the Loyang Lane, And turn to Loyang way slowly, suddenly the Lorry GBD5282A drive straight and hit my car from right corner.



A: SLW 4460 R
B: GBD 5282A

Declaration


We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature / Date & Time

24/03/2021 @ 22:00pm

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel