

ASS. REC BY:

AG

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report

GIA / PR Seen:

Est Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp Reading

Eng/No:

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ SRim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

R/Bal

L/Bal

D.O.A

Rear

R/Bal

L/Bal

D.O.I

Survey held at

Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☒ N/S / ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No Body Injured

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Inspector's Name

Inspector's Signature

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp. (\$☐ : Other (\$

Survey Fee:

Transportation:

3 + RS \$

Analysis

Other:

TOTAL

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SEAH SOON HONG FREDDY
56 PARK VILLAS RISE

SINGAPORE 545352

Estimate No: MC1901844
Date: 24 Mar 2021
Policy No: P2286695
Veh Reg No: SBZ2969G
Make/Model: SKODA KODIAQ 2.0 TSI 4X4

ATTN:

Your Ref No: SBZ2969G
Claim Type: Third Party
Accident Date: 23/03/2021
TP Veh Reg No: GBK7352G

Estimate Repair Cost to Vehicle No :SBZ2969G

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 FRONT DOOR LH <i>— buc</i>	1 PC	2,875.00	
2 FRONT DOOR PROTECTOR LH <i>— mrc</i>	1 PC	372.00	
3 FRONT DOOR RUBBER (AT DOOR) LH <i>X 4NN</i>	1 PC	186.00	
4 FRONT DOOR RUBBER (AT DOOR) TOP LH <i>X 4NN</i>	1 PC	462.00	
5 SIDE MIRROR COVER LOWER W MOTOR ARM LH <i>— cut.</i>	1 PC	891.25	
6 SIDE MIRROR SIGNAL LAMP LH <i>?</i>	1 PC	128.15	
		4,914.40	
	Less 10%	491.44	4,422.96
Special Nett			
7 SIDE MIRROR COVER W WRAPPER LH - CHECK PRICE <i>— cut.</i>	1 PC	0.00	
8 CERAMIC PAINTING @ FRONT DOOR LH <i>— provide previous invoice.</i>	1 PC	200.00	
		200.00	200.00
LABOUR			
9 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20
10 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	120.00	60.
11 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	30.00	X NN
12 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR FRONT INNER PANELS INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	300.00	200.
13 TO SPRAY FRONT DOOR LH,SIDE MIRROR COVER LH.	1 PC	300.00	250.
		790.00	790.00

3 Days -
P/P. before print photos.
Cmo Qiang - 8288082
21/3/2021



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL. 6483 1244 (4 lines) FAX 6483 6170 Email: ahlmmc@singnet.com.sg
GST M9-0009639-E RCB NO 06470300B

SURVEYOR COPY

M/S : SEAH SOON HONG FREDDY
56 PARK VILLAS RISE

SINGAPORE 545352

ATTN:

Your Ref No: SBZ2969G
Claim Type: Third Party
Accident Date: 23/03/2021
TP Veh Reg No: GBK7352G

Estimate No: MC1901844
Date: 24 Mar 2021
Policy No: P2286695
Veh Reg No: SBZ2969G
Make/Model: SKODA KODIAQ 2.0 TSI
4X4

Estimate Repair Cost to Vehicle No :SBZ2969G

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 5,412.96
		Add GST @ 7%	378.91
		Total Amount Payable	S\$ 5,791.87

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SEVEN HUNDRED NINETY ONE AND CENTS EIGHTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

AUTHORIZED SIGNATURE


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: