

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ms: **AIG Asia Pacific Insurance Pte Ltd**

Date: 23/03/2021

Attn : **MOTOR CLAIMS DEPT**

ESTIMATE

VEHICLE NO: SLC5856G

CHASSIS NO : NSP1707022182

MAKE / MODEL : Toyota Sienta 1.5X Auto

DATE OF ACCIDENT : 05/03/2021

YOUR INSURED VEHICLE NUMBER : SMF813K

MILEAGE : 330869 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	R/R fender <i>X R</i>	1PC	\$ 1,500.00	\$ 1,500.00
2	R/R fender outer side rubber moulding <i>/scr</i>	1PC	\$ 180.00	\$ 180.00
3	R/R sliding door assy <i>/pn</i>	1PC	\$ 1,800.00	\$ 1,800.00
4	R/R door outer side rubber moulding <i>/scr</i>	1PC	\$ 380.00	\$ 380.00
LIST TOTAL S\$:				\$ 3,480.00
25.00% DISCOUNT S\$:				\$ 870.00
				\$ 2,610.00

LABOUR CHARGES

1 To labour charge for removing R/R fender and R/R door out to facilitate repairs and replacement of damaged parts \$ 900.00 *300*

2 To respray R/R fender, R/R sliding door \$ 800.00 *500*

LABOUR TOTAL S\$:

\$ 1,700.00

TOTAL S\$:

\$ 4,310.00

7% GST

\$ 301.70

GRAND TOTAL S\$:

\$ 4,611.70

Repair day - 3 days

L1S

After paint photo

Sun Pin(Lkl)

24/03/2021

TP without prejudice