

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms: AIG Asia Pacific Insurance Pte Ltd
Date: 23/03/2021
Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLC5856G
CHASSIS NO: NSP1707022182
MAKE / MODEL: Toyota Sienta 1.5X Auto
DATE OF ACCIDENT: 05/03/2021
YOUR INSURED VEHICLE NUMBER: SMF813K
MILEAGE: 330869 km

	PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1	R/R fender X R	1PC	\$ 1,500.00	\$ 1,500.00X
2	R/R fender outer side rubber moulding / Sck	1PC	\$ 180.00	\$ 180.00 120
3	R/R sliding door assy / PD	1PC	\$ 1,800.00	\$ 1,800.00 1,350
4	R/R door outer side rubber moulding / Sck	1PC	\$ 380.00	\$ 380.00 180
LIST TOTAL S\$:				\$ 3,480.00 1,650
25.00% DISCOUNT S\$:				\$ 870.00 -25%
				\$ 2,610.00 1,237.50

LABOUR CHARGES

1	To labour charge for removing R/R fender and R/R door out to facilitate repairs and replacement of damaged parts	\$ 900.00	300 250
2	To respray R/R fender, R/R sliding door	\$ 800.00	500
LABOUR TOTAL S\$:		\$ 1,700.00	800
TOTAL S\$:		\$ 4,310.00	
7% GST		\$ 301.70	
GRAND TOTAL S\$:		\$ 4,611.70	

Repair day - 3 days

LIS
After paint photo
Sun Pin (Lkl)
24/03/2024
Tp without prejudice

1,237.50
800
2,037.50
- 20%
1,630

LIS
\$1,650
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: