



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 3230R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	WINDSCREEN FRT	SCRATCHED	191.00	191.00
1	PLATE LIGHT	SERVICEABLE	177.00	-
1	WIND SCREEN HOLDER (L)	CRACKED	76.00	76.00
1	METER HOLDER STRUCTURE (L)	CRACKED	218.00	218.00
1	METER HOLDER STRUCTURE (R)	CRACKED	218.00	218.00
1	HANDLE BAR (L)	BENT	24.00	24.00
1	HANDLE GRIP (L)	MISSING	19.00	19.00
1	SIGNAL SWITCH	BROKEN	169.00	169.00
1	CLUTCH LEVER	CUT	61.00	61.00
1	FRONT SIGNAL (L)	CUT	65.00	65.00
1	FRONT FAIRING (L)	CUT	244.00	244.00
1	SIDE STAND	TO REPAIR SEE LABOUR	73.00	-
1	SIDE STAND BASE PP	TO REPAIR SEE LABOUR	185.00	-
1	FOOTREST / REAR / (L)	CUT	34.00	34.00
1	SIGNAL / REAR / (L)	CUT	65.00	65.00
1	REAR SEAT	TORN	506.00	506.00
1	REAR SEAT COWLING	CRACKED	102.00	102.00
1	TAIL LIGHT	BROKEN	136.00	136.00
1	CHAIN COVER	CRACKED	32.00	32.00
1	FOOTREST KIT / FRONT / P.P.	BENT / TWISTED	1,122.00	1,080.00
1	WHEEL RETAINER / REAR / P.P.	CUT	65.00	65.00
1	KEY LOCK COVER	MISSING	7.00	7.00
1	MIRROR / L / P.P	BROKEN	104.00	104.00
	LESS 10% DISCOUNT		-	-341.60
			3,893.00	3,074.40
	<u>SPECIAL NETT ITEMS</u>			
1	NO. PLATE FRONT/STICKER (SN)	SCRATCHED	15.00	10.00
1	I.U. UNIT (SN)	CRACKED	155.00	155.00

Report Ref No. CS/SMO21003825/Uvf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	HANDPHONE HOLDER (SN) <u>LABOUR</u> LABOUR. INCLUSIVE OF THE REPAIR OF SIDE STAND AND SIDE STAND BASE PP.	BENT	85.00	60.00
			255.00	225.00
			320.00	320.00
			320.00	320.00
GRAND TOTAL			4,468.00	3,619.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS/SMO21003825/Uvf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.