



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21003825/Uvf3e2	
			Date: 23/06/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 8554C	Veh. Inspected	FBM 3230R	
Policy No.	D20MTRENT000308	Coverage (\$)	0.00	
Claim No.	CMTD2100838/SYH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	25/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	K.T.M. RC200	c.c	200	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VBKJYC405FC006200	Colour	BLACK	
Odometer	91245 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110-70-17	BRIDGESTONE	7 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	150-60-17	BRIDGESTONE	7 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/03/2021	Inspection Date	29/03/2021	
Survey held at	DIRT WHEEL MOTOR TRADING BLK 9004 #01-100 TAMPINES ST 93 SINGAPORE 528838			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	