

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBE 10752

at Workshop m/s

Auto bay

of

Insured:

SMG 76356

Policy No.

PMPCSNW0018257200

Claims No.

SNM210201626 (CO2) LEWLC

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

8351.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

to 2E

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBE 10752

Yr Regn:

2/9/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(m)

Make:

NISSAN NV200

c.c

1461

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp.Reading

116576

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VSKYRAM2020109845

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175-70 R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Greenlander

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/3/1

D.O.I.

25/3/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MTA 817172 Dep flk.

5/4/21 2/5 \$ 4000 continued with victor (Red \$ 6550.62, 62%)
05/4/21 @ 10.25am revised to Jenny Lew via Melissa.

Date/Time, File Pass to?

1) 05/4/21

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

___ S + RS ___ SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

NER-TP

Lump Sum / I.B.I. (\$

4000

)

Not Authorized
Heli
25/3/21
2/5 \$4000
5 days

submit to insurance.

Regn No : GBE1075C

Vehicle Make & Model : Nissan NV200

ITEM NO	DESCRIPTION OF ITEMS	QUANTITY (Piece/Set)	UNIT PRICE (S\$)	AMOUNT (S\$)
Nett				
List Items:				
1	Rear taillamp <i>nn</i>	2	\$ 488.80	\$ 977.60 X
2	Rear bumper <i>DD</i>	1	\$ 899.80	\$ 899.80
3	Rear bumper side retainer <i>nn</i>	2	\$ 69.40	\$ 138.80 X
4	Rear end panel <i>Def</i>	1	\$ 966.80	\$ 966.80
5	Rear end panel inner garnish <i>twi</i>	1	\$ 98.20	\$ 98.20
6	Rear windscreen seal <i>NS</i>	1	\$ 165.00	\$ 165.00 X
7	Rear tailgate (LH) <i>Body</i>	1	\$ 1,285.00	\$ 1,285.00
8	Rear tailgate (RH) <i>Body</i>	1	\$ 1,468.50	\$ 1,468.50
9	Rear tailgate rubber <i>twi</i>	1	\$ 189.30	\$ 189.30
10	Rear tailgate emblem "NV200" <i>rec</i>	1	\$ 72.00	\$ 72.00
11	Rear tailgate emblem "NISSAN" <i>rec</i>	1	\$ 68.50	\$ 68.50
12	Rear tailgate emblem "DCI" <i>rec</i>	1	\$ 65.50	\$ 65.50
13	Rear tailgate outer handle <i>nn</i>	1	\$ 172.50	\$ 172.50 X
14	Rear tailgate inner lock <i>lower</i>	1	\$ 183.90	\$ 183.90
15	Rear tailgate inner trim board <i>nn</i>	2	\$ 285.20	\$ 570.40 X
			Sub-total	\$ 7,321.80
			Less 10%	\$ 732.18
Nett List Items			Total	\$ 6,589.62
Special Nett Items:				
1	Reverse sensor <i>shorted</i>	1 set	\$ 280.00	\$ 280.00 200
2	Reverse camera <i>nn</i>	1	\$ 380.00	\$ 380.00 X
3	Rear tailgate "70 km/h" sticker <i>rec</i>	1	\$ 28.00	\$ 28.00 10
4	Rear tailgate "6 pax" sticker <i>rec</i>	1	\$ 28.00	\$ 28.00 10
5	Rear number plate with holder <i>nn</i>	1	\$ 45.00	\$ 45.00 X
6	Rear tailgate glass sealant <i>rec</i>	1	\$ 180.00	\$ 180.00 70
S/Nett Items			Total	\$ 941.00
Labour Charge Items:				
1	To checking electrical wiring and check functions		\$ 20	\$ 80.00
2	To remove and replace damaged taillamps		\$ 11	\$ 180.00 X
3	To remove and refit glass (LH/RH)		\$ 200	\$ 360.00
4	To remove and replace reverse sensor		\$ 50	\$ 80.00
5	To respray undercoating/rust proofing		\$ 80	\$ 120.00
6	To respray painting & etc		\$ 600	\$ 1,200.00
7	Panel beating, cut, weld, remove and replacing above parts		\$ 600	\$ 1,000.00
			Labour Charge	\$ 3,020.00
			Grand total	\$ 10,550.62

Estimate Parts & Labour

LKK Auto Consultants hence notify the Repairer of the following:
• To respray for spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-352290

10%

P-3170-61

S/N-290

H-1550

5010-61