

8 Kaki Bukit Ave 4 #08-45/46 Premier@ Kaki Bukit S415875
Tel: 6702 1555 Fax: 6702 1444 ROC No. : 201500047H

ESTIMATE

TO : ECICS	DATE : 24-Mar-2021
ATTENTION : MOTOR CLAIM DEPARTMENT	JOB TYPE : THIRD PARTY CLAIM
VEHICLE DETAILS	
VEHICLE NO. : SMG5819G	<i>Veron.</i>
MAKE / MODEL : HONDA SHUTTLE	
CHASSIS NO. : GP7-121537	
OWNER INSURANCE : NTUC INCOME	ACCIDENT DETAIL
POLICY NO. : 5106525192-02	DATE : 20-Mar-2021
	TIME : 12:10 hr
PERSON INCHARGE : Falcoe T: 6702 1555 F: 6702 1444 falcolee@skauto.com.sg	

CLAIM DETAIL : LIST PRICE (\$\$)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Bonnet	1	\$ 810.00	\$ 810.00
2	Bonnet Seal LH / RH	2	\$ 48.70	\$ 97.40
3	Bonnet Hinge LH / RH	2	\$ 59.40	\$ 118.80
4	Bonnet Lock Assy	1	\$ 146.10	\$ 146.10
5	Front Bumper	1	\$ 1,025.00	\$ 1,025.00
6	Front Bumper Fog Lamp Garnish	1	\$ 101.00	\$ 101.00
7	Front Bumper Retainer LH / RH	2	\$ 34.50	\$ 69.00
8	Front Bumper Reinforcement	1	\$ 421.10	\$ 421.10
9	Front Bumper Lower Cover	1	\$ 312.00	\$ 312.00
10	Front Bumper Lower Grille	1	\$ 289.00	\$ 289.00
11	Headlamp LH	1	\$ 2,450.00	\$ 2,450.00
12	Headlamp Chrome	1	\$ 198.00	\$ 198.00
13	Headlamp Lower Bracket	1	\$ 91.80	\$ 91.80
14	Front Windscreen Moulding	1	\$ 233.00	\$ 233.00
15	Front Windscreen LH Garnish	1	\$ 212.00	\$ 212.00
16	Front Fender LH	1	\$ 511.60	\$ 511.60
17	Front Fender Side Frame LH	1	\$ 697.00	\$ 697.00
18	Front Fender "HYBRID" Emblem	1	\$ 68.00	\$ 68.00
19	Front Fender Inner Wheel Lining	1	\$ 151.40	\$ 151.40
20	Front Support Panel	1	\$ 750.00	\$ 750.00
21	Front Support Panel Top Garnish	1	\$ 312.00	\$ 312.00
22	Front Support Under Panel	1	\$ 189.00	\$ 189.00

23	Front Knuckle Arm LH	1	\$	325.00	\$	325.00	+
24	Front Knuckle Bearing LH	1	\$	180.00	\$	180.00	+
25	Front Stabiliser Linkage LH	1	\$	68.00	\$	68.00	+

Front LH Fender Bracket 105 ✓

Best

4435.30

3548.24

TOTAL PRICE : \$ 9,826.20

LIST LESS 20% : \$ 1,965.24

SUB TOTAL PRICE : \$ 7,860.96

CLAIM DETAIL : PARTS S/NETT

S/N	DESCRIPTION	QTY	UNIT S/N PRICE	TOTAL S/N PRICE
1	Front Bumper Clip <i>Neu</i>	1	\$ 50.00	\$ 50.00
2	Front Fender Inner Shield Clip <i>Neu</i>	1	\$ 50.00	\$ 50.00
3	Front Windscreen LH Garnish clips	1	\$ 48.00	\$ 48.00
4	Front Support Panel Top Garnish Clip <i>Neu</i>	1	\$ 60.00	\$ 60.00
5	Front Windscreen Sealant <i>Neu</i>	1	\$ 80.00	\$ 80.00
6	Front LH Quarter Glass Sealant <i>Neu</i>	1	\$ 60.00	\$ 60.00
7	Front Parking Sensor <i>Neu</i>	1	\$ 280.00	\$ 280.00
8	Yokohama BluEarth-GT AE51 185/60R15 Tyre <i>Neu</i>	1	\$ 312.00	\$ 312.00
9	Honda 15" Wheel Cover <i>Cut</i>	1	\$ 78.00	\$ 78.00

S/N TOTAL PRICE: \$ 1,018.00

178.

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	DESCRIPTION	PRICE	ADJUST
1	Labour charge to cut/weld/straighten damaged areas and replc above mentioned body parts	\$ 840.00	500
2	To spray paint Frt Bumper, Bonnet, Frt LH Fender, Frt LH Door, Frt Outer A Pillar and other affected areas	\$ 1,400.00	800 800
3	To perform 4 wheel alignment	\$ 180.00	80.
4	Labour charge to rem/refit and replc Front LH undercarriage components to facilitate repair	\$ 280.00	X.
5	Labour charge to troubleshoot, front portion wiring and other electrical components to facilitate repair	\$ 180.00	30
6	Labour charge to rem-refit front LH Quarter glass to facilitate repair	\$ 180.00	40
7	Labour charge to apply anti-rust and tuff kote to front portion repaired panels	\$ 120.00	40
8	Labour charge to install & calibrate LH headlamp with height levelling for LTA compliance	\$ 160.00	X
9	To install front reverse parking sensor with calibration	\$ 180.00	50

LABOUR TOTAL PRICE: \$ 3,520.00

1540

ESTIMATE REPORT

TOTAL PARTS PRICE : \$	8,878.96
TOTAL LABOUR PRICE : \$	3,520.00
TOTAL AMOUNT : \$	12,398.96

12,482.96

APPROVED DETAILS

NO.OF REPAIR DAYS :

P & P OR LUMPSUM :

SURVEYED BY :

CONTACT NUMBER :

E-MAIL :

Adrian Lj
L/S 25/03/21

04 Days.

total: 5266.24.

L/S: A.2K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: