

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SMR2139Y
Accident Date : 23-Mar-2021

No. : 06363

Date : 24-Mar-2021

Our Ref : 021045 (AIG) / CHAN

PAGE : 1

CHIA EU-GENE BRYAN
37 JALAN REDOP
Singapore 808583

ESTIMATED COST OF REPAIR FOR BMW X3 SDRIVE 2.0 SPORT SLH6000B

1 pc	Rear bumper fascia (M sport)	2,300.00
1 pc	Rear n/s bumper reflector	77.80
1 pc	Rear bumper lower spoiler	392.50
1 pc	Rear n/s exhaust chrome pipe	191.85
1 pc	Rear n/s parking sensor	257.90
1 pc	Rear n/s parking sensor o ring	12.50
1 pc	Rear n/s bumper bracket	194.20
1 pc	Rear n/s fender air vent	180.50

3,607.25

Less 5% : 180.36

3,426.89

1 pc Rear bumper clip & reivet

50.00 sn

To rewiring rear parking sensor
wire

40.00

To remove rear exhaust for renew
chrome pipe

30.00

To putty and spray replaced parts

600.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

500.00

Total : S\$ 4,646.89

=====

Singapore Dollars Four Thousand Six Hundred and
Forty Six and Cents Eighty Nine Only