

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21003857/GVF3E2

**Date:** 07/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070106817  
Claimant Vehicle No : SJT3710R Insured Vehicle No : SMT7845Z  
Date of Loss: 17/03/2021 Nature of Claim: TP Claim No: 9752553478SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJT3710R**  
Make & Model: HONDA STREAM, 1.8 L RSZ (A) Engine No: R18A13850352  
Reg. Date: 05/10/2009 (Man. Year: 2009) Chassis No: JHMRN68809C200352  
Colour: Black Odometer: 162016 km  
Engine Capacity: 1799 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18  
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 25/03/2021  
Date Inspected: 29/03/2021 Inspected At: Lim Motor Pte Ltd (HQ)  
160 Sin Ming Drive, #05-20 Autocity  
Singapore 575722  
Estimated Period of Repair: 3.0 days

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Buckled	0.00 F	*- F
2	1		*FRT RH DOOR GLASS REGULATOR	Bent	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >