

Little History

not Authorised

25/3/21

1/5 = 7600
Substr. After repair

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3020/03/21

Your Ref:

Date: 25th March 2021

3 days

ANANKUMAR S/O VIJAYAKUMAR
BLK 432C, #07-553
YISHUN AVENUE 1,
SINGAPORE 763432

Estimate cost of repair to AUDI A4 (A) 2.0 TFSI Saloon - SPJ 4005 L

1 pc front bumper	de/wopnd	1610.95	\$ 1,610.95
1 pc front bumper o/s side retainer	11		25.55 X
1 set front bumper clips & revets	new	60	169.55
1 pc front bumper o/s sensor	src		208.85 X
1 pc o/s head lamp assy	src		7,486.65 X
1 pc front o/s fender	as/rent		575.25
1 pc front o/s fender inner shield	11		177.25 X
1 set front o/s fender inner shield clips & revets	11		53.85 X
1 pc front o/s sport rim	11		1,629.90 X

\$ 11,637.80

Less 40%

\$ 4,463.78

\$ 10,474.02

To wiring check up & adjust headlight alignment.

50.00

20

To check & adjust front wheel alignment & balancing.

11 120.00

X

To diagnose & re-set head light fault code for refix.

120.00

50

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts.

750.00

300

To putty & respray painting on all affected accident parts.

950.00

450

To respray Tuff-Kote on all affected accident parts.

50.00

30

\$ 12,514.02

=====

Dollars : Twelve Thousand Five Hundred Fourteen And Cents Two Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-9732.8
102
1-8759.56
1-850
9609.16
202
7687.