

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

25-Mar-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHC 6047 R

1 pc	Wheel cover	\$	346.40
1 pc	Rear bumper	\$	459.40
1 pc	Rear bumper o/s side bracket	\$	33.10
1 pc	Rear o/s rim	\$	1,091.50
1 pc	Rear o/s lower arm	\$	393.10
1 pc	Rear o/s assist arm	\$	92.80
1 pc	Rear o/s trailing arm	\$	121.00
1 pc	Rear o/s shock absorber	\$	230.50
1 pc	Rear o/s knuckle bearing	\$	454.00
1 pc	Rear o/s knuckle arm	\$	386.90
		\$	3,608.70
		Less 20%	\$ 721.74
		\$	2,886.96

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	o/s door stickers	\$	100.00
1 pc	Rear o/s fender sticker	\$	60.00
1 pc	Rear o/s tyre	\$	200.00
1 set	Rear o/s fender inner shield clips	\$	28.00
1 set	Sealant	\$	50.00
To dismantle and replace the rear o/s undercarriage		\$	250.00
To check rear o/s wheel alignment		\$	80.00
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender etc		\$	800.00
To putty and spray painting on rear o/s door, o/s rocker panel garnish, rear o/s fender, rear bumper		\$	800.00
To apply rustproof on repaired panels		\$	150.00
		\$	5,752.96