

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

25-Mar-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHC 6047 R

1 pc	Wheel cover	\$	346.40	<i>cut</i>
1 pc	Rear bumper	\$	459.40	<i>Rp</i>
1 pc	Rear bumper o/s side bracket	\$	33.10	<i>x</i>
1 pc	Rear o/s rim	\$	1,091.50	<i>x</i>
1 pc	Rear o/s lower arm	\$	393.10	<i>?</i>
1 pc	Rear o/s assist arm	\$	92.80	<i>x</i>
1 pc	Rear o/s trailing arm	\$	121.00	<i>x</i>
1 pc	Rear o/s shock absorber	\$	230.50	<i>x</i>
1 pc	Rear o/s knuckle bearing	\$	454.00	<i>?</i>
1 pc	Rear o/s knuckle arm	\$	386.90	<i>?</i>
		\$	3,608.70	
		\$	721.74	<i>Loss 20%</i>
		\$	2,886.96	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/NETT

1 set	Rear bumper clips	\$	48.00	<i>x</i>
1 set	o/s door stickers	\$	100.00	<i>Bones</i>
1 pc	Rear o/s fender sticker	\$	60.00	<i>40.00</i>
1 pc	Rear o/s tyre	\$	200.00	<i>x</i>
1 set	Rear o/s fender inner shield clips	\$	28.00	<i>x</i>
1 set	Sealant	\$	50.00	<i>x</i>
To dismantle and replace the rear o/s undercarriage		\$	250.00	<i>100? plus</i>
To check rear o/s wheel alignment		\$	80.00	<i>✓</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00	<i>x</i>
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00	<i>30</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender etc		\$	800.00	<i>400</i>
To putty and spray painting on rear o/s door, o/s rocker panel garnish, rear o/s fender, rear bumper		\$	800.00	<i>600</i>
To apply rustproof on repaired panels		\$	150.00	
		\$	5,752.96	

Tanphk 97895747
up! 25/3/21 @ 450pm
p/p Resurvey new parts, after repair
03 days
Tanphk @ 11h40 to 11h45